

School Assessment Report



Type: High Schools
School: Yates High School
Date: Jul 16, 2012

Final

Table of Contents

| | |
|--|----|
| Executive Summary | 4 |
| Condition Budget Summary | 4 |
| Educational Suitability Summary | 6 |
| Site | 7 |
| Site Summary | 7 |
| Deficiency Condition Budget Summary: Site | 8 |
| Site Deficiencies Budget Detail | 9 |
| Site Deficiency Priority | 9 |
| Site Condition Deficiencies | 10 |
| Site Deficiencies Budget Narrative | 11 |
| Buildings | 16 |
| Building: Boys Weight Room | 16 |
| Building Condition Budget Summary | 16 |
| Building Condition Budget Detail | 16 |
| Building Deficiency Priority | 17 |
| Building Condition Deficiencies | 18 |
| Building Condition Deficiencies Narrative | 19 |
| Building: Girls Weight Room | 28 |
| Building Deficiency Condition Budget Summary | 28 |
| Building Deficiency Condition Budget Detail | 28 |
| Building Deficiency Priority | 29 |
| Building Deficiencies Budget Detail | 30 |
| Building Deficiencies Budget Narrative | 31 |
| Building: Greenhouse | 41 |
| Building Deficiency Condition Budget Summary | 41 |
| Building Deficiency Condition Budget Detail | 41 |
| Building Deficiency Priority | 41 |
| Building Deficiencies Budget Detail | 42 |
| Building Deficiencies Budget Narrative | 43 |
| Building: Main | 44 |
| Building Deficiency Condition Budget Summary | 44 |
| Building Deficiency Condition Budget Detail | 44 |
| Building Deficiency Priority | 45 |
| Building Deficiencies Budget Detail | 46 |
| Building Deficiencies Budget Narrative | 47 |

| | |
|----------------------------------|----|
| Appendix 1 - Assessment Criteria | 61 |
| Glossary | 62 |

Final

Executive Summary

School Name: Yates High School

| | |
|---------------------------------|--------------|
| Number of Buildings: | 4 |
| Gross Area (SF): | 198,798 |
| Replacement Value: | \$55,184,994 |
| Condition Budget: | \$19,496,738 |
| Total FCI: | 35.33% |
| Total RSLI: | 10% |
| Total CFI: | 35.3% |
| Condition Score: | 64.67 |
| Suitability, Educational Score: | 70.49 |
| Suitability, Tech Read Score: | 54.25 |
| Suitability, Total Score: | 67.24 |
| School Score: | 65.96 |



Summary:

Yates High School campus is located at 3703 Sampson Street, Houston TX, and consists of 1 main school building. The original campus was constructed in 1958 and an addition to the main school building was constructed in 1985. Ancillary buildings on campus include, a boy's weight room, a girl's weight room, a Greenhouse and T-Buildings. In addition to the buildings, the campus contains covered walkways, tennis courts, basketball hard courts practice football field and a track. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for each building and other facilities on the campus.

Condition Budget Summary


Building condition is evaluated based on the functional elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a building cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this facility.

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|---------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| A20 Basement Construction | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 0% | 45.00% | \$2,754,736 |
| B30 Roofing | 55% | 0.00% | \$0 |
| C10 Interior Construction | 0% | 49.56% | \$1,580,522 |
| C20 Stairs | 12% | 0.00% | \$0 |
| C30 Interior Finishes | 7% | 51.62% | \$2,921,766 |
| D10 Conveying | 97% | 0.00% | \$0 |
| D20 Plumbing | 0% | 100.00% | \$2,899,601 |
| D30 HVAC | 35% | 38.59% | \$3,251,736 |
| D40 Fire Protection | 21% | 97.74% | \$261,931 |
| D50 Electrical | 11% | 21.02% | \$1,353,553 |
| E10 Equipment | 24% | 0.00% | \$0 |
| E20 Furnishings | 0% | 110.00% | \$725,735 |

| Unifomat Classification | RSLI | SCI | Condition Budget |
|-------------------------------|------|---------|------------------|
| F10 Special Construction | 0% | 110.00% | \$1,200,124 |
| G20 Site Improvements | 17% | 58.51% | \$1,943,991 |
| G30 Site Mechanical Utilities | 1% | 86.76% | \$603,044 |
| G40 Site Electrical Utilities | 93% | 0.00% | \$0 |
| | | Total: | \$19,496,738 |

Condition Deficiency Priority

| Building /Site | GSF | FCI | Condition Budget | | | | | |
|-------------------|---------|-------|------------------|------------|--------------|------------|------------|--------------|
| | | | Priority 1 | Priority 2 | Priority 3 | Priority 4 | Priority 5 | Total |
| Boys Weight Room | 4,773 | 30.4% | \$0 | \$0 | \$373,294 | \$0 | \$0 | \$373,294 |
| Girls Weight Room | 1,964 | 55.1% | \$0 | \$0 | \$274,651 | \$0 | \$0 | \$274,651 |
| Greenhouse | 2,400 | 100% | \$0 | \$0 | \$256,608 | \$0 | \$0 | \$256,608 |
| Main | 189,661 | 33.0% | \$0 | \$0 | \$16,045,150 | \$0 | \$0 | \$16,045,150 |
| Site | | 55.0% | \$0 | \$0 | \$2,547,035 | \$0 | \$0 | \$2,547,035 |
| Total: | 198,798 | 35.3% | \$0 | \$0 | \$19,496,738 | \$0 | \$0 | \$19,496,738 |



3 - Short Term Conditions (2-3 Years) \$19,496,738

School Condition Budget: \$19,496,738

Final

Educational Suitability Summary

The MGT BASYS-generated document appended to this report provides information about the Educational Suitability of this school, based on the site visit using MGT's ESA guidelines. Each area was scored 5, 4, 3, 2, 1, or N/A with 1 being a high score. Items are scored N/A if they are not appropriate to that school program (e.g., football fields at an elementary school or preschool at a high school) or are not needed at a school. All scores are shown in the narrative supporting the score.

Final

Site

Site Summary

Site condition is evaluated based on the functional elements of a site and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this facility.



| | | | |
|--------------------|-------------|-------------------|-------------|
| Site Acreage | | Condition Budget: | \$2,547,035 |
| Replacement Value: | \$4,626,825 | Total FCI: | 55.05% |
| | | Total RSLI: | 25% |

Site:
Yates High School original site was originally constructed in 1958. The site is occupied by 4 permanent structures and 3 temporary buildings. Campus site features include; paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, fencing, football practice field, track, basketball hardcourt, abandoned practice baseball field and tennis courts. Site mechanical and electrical features include water, sewer, natural gas, and site lighting. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for the site features.

Final

Deficiency Condition Budget Summary: Site

Site condition is evaluated based on the functional elements of a site and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this site.

| Unifomat Classification | RSLI | SCI | Condition Budget |
|-------------------------------|------|---------------|--------------------|
| G20 Site Improvements | 17% | 58.51% | \$1,943,991 |
| G30 Site Mechanical Utilities | 1% | 86.76% | \$603,044 |
| G40 Site Electrical Utilities | 93% | 0.00% | \$0 |
| | | Total: | \$2,547,035 |

Final


Site Deficiencies Budget Detail

Site condition is evaluated based on the functional elements of a site and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this site.

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|--|------------|------|--------------|-------------------|-------------|------|--------|------------------|
| G2010 | Roadways | \$1.56 | 25 | 1986 | 2011 | \$418,669 | 0% | 110% | \$460,535 |
| G2020 | Parking Lots | \$4.01 | 25 | 1986 | 2011 | \$1,076,193 | 0% | 100% | \$1,076,193 |
| G2020 | Pedestrian Paving - sidewalks, etc | \$1.62 | 30 | 1986 | 2016 | \$434,771 | 13% | 0.00% | \$0 |
| G2040 | Baseball Field | \$0.16 | 30 | 1958 | 1988 | \$42,940 | 0% | 100% | \$42,940 |
| G2040 | Basketball / hard court play area | \$0.10 | 10 | 2010 | 2020 | \$26,838 | 80% | 0.00% | \$0 |
| G2040 | Canopy | \$0.24 | 30 | 1986 | 2016 | \$64,411 | 13% | 0.00% | \$0 |
| G2040 | Football Field Natural Turf | \$0.15 | 10 | 1958 | 1968 | \$40,257 | 0% | 100% | \$40,257 |
| G2040 | Site Development | \$1.15 | 30 | 1958 | 1988 | \$308,634 | 0% | 105% | \$324,066 |
| G2040 | Tennis Court (s) | \$1.40 | 10 | 2010 | 2020 | \$375,728 | 80% | 0.00% | \$0 |
| G2040 | Track Synthetic Surface - Resurface only | \$0.50 | 10 | 2010 | 2020 | \$134,189 | 80% | 0.00% | \$0 |
| G2050 | Landscaping | \$1.49 | 10 | 2010 | 2020 | \$399,882 | - | 0.00% | \$0 |
| G3010 | Water Supply | \$0.45 | 50 | 1958 | 2008 | \$120,770 | 0% | 0.00% | \$0 |
| G3020 | Sanitary Sewer | \$1.25 | 50 | 1958 | 2008 | \$335,472 | 0% | 105% | \$352,245 |
| G3030 | Storm Sewer | \$0.89 | 50 | 1958 | 2008 | \$238,856 | 0% | 105% | \$250,799 |
| G4020 | Site Lighting | \$2.27 | 30 | 2010 | 2040 | \$609,216 | 93% | 0.00% | \$0 |
| Total | | \$17.24 | | | | \$4,626,825 | 25% | 55.05% | \$2,547,035 |

Site Deficiency Priority

Site Deficiencies by Priority:




3 - Short Term Conditions (2-3 Years) \$2,547,035

Site Condition Budget: \$2,547,035

Site Condition Deficiencies

Current deficiencies included systems that have reached or exceeded their design life or components of the systems that are in need of repair. Systems that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Expected Life'. The following chart includes all current deficiencies associated with this site.



Site Condition Budget: \$2,547,035

Final

Site Deficiencies Budget Narrative

Current deficiencies included systems that have reached or exceeded their design life or components of the systems that are in need of repair. Systems that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Expected Life'. The following chart includes all current deficiencies associated with this site.



System: G2010 - Roadways

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 25-year service life which expired in 2011.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The driveways are beyond useful life and require replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$460,535



System: G2020 - Parking Lots

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 25-year service life which expired in 2011.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The parking lots are beyond useful life and require replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$1,076,193

Final

System: G2020 - Pedestrian Paving - sidewalks, etc

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.



System: G2040 - Baseball Field

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The practice baseball field has been abandoned and is beyond useful life.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$42,940

System: G2040 - Basketball / hard court play area

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 10-year service life. Based on the assessment, it is expected to expire in 2020.

Recommendation: No action is required.

System: G2040 - Canopy

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

Final



System: G2040 - Football Field Natural Turf

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 10-year service life which expired in 1968.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The football field is beyond its useful life.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$40,257



System: G2040 - Site Development

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The fencing inside the perimeter are beyond useful life and require replacement. The grounds have random holes.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$324,066

System: G2040 - Tennis Court (s)

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 10-year service life. Based on the assessment, it is expected to expire in 2020.

Recommendation: No action is required.

Final

System: G2040 - Track Synthetic Surface - Resurface only

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 10-year service life. Based on the assessment, it is expected to expire in 2020.

Recommendation: No action is required.

System: G2050 - Landscaping

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 10-year service life. Based on the assessment, it is expected to expire in 2020.

Recommendation: No action is required.

System: G3010 - Water Supply

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 50-year service life which expired in 2008. However, based on the 2009 assessment, the service life has been extended to 2017.

Recommendation: No action is required.



System: G3020 - Sanitary Sewer

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 50-year service life which expired in 2008.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The sanitary sewer system is beyond useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$352,245

Final



System: G3030 - Storm Sewer

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 50-year service life which expired in 2008.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The storm sewer system is beyond useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$250,799

System: G4020 - Site Lighting

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 30-year service life. Based on the assessment, it is expected to expire in 2040.

Recommendation: No action is required.

Final

Buildings

Building Name: Boys Weight Room

Year Built: 1958
Gross Area (SF): 4,773

The Yates High School Boy's Weight Room Building is a 1-story building. Originally built in 1958 there have been no additions or renovations. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Condition Budget Summary

Building condition is evaluated based on the functional elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a building cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this facility.

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|---------------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 0% | 42.77% | \$78,463 |
| B30 Roofing | 55% | 0.00% | \$0 |
| C10 Interior Construction | 0% | 49.57% | \$46,471 |
| C30 Interior Finishes | 4% | 71.43% | \$136,371 |
| D20 Plumbing | 0% | 110.00% | \$90,371 |
| D30 HVAC | 49% | 0.00% | \$0 |
| D40 Fire Protection | 86% | 0.00% | \$0 |
| D50 Electrical | 17% | 0.00% | \$0 |
| E20 Furnishings | 0% | 110.00% | \$21,618 |
| | | Total: | \$373,294 |


Building Condition Budget Detail

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|----------------------|------------|------|--------------|-------------------|-------------|------|--------|------------------|
| A1010 | Standard Foundations | \$9.24 | 100 | 1958 | 2058 | \$59,538 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$7.99 | 100 | 1958 | 2058 | \$51,484 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$14.99 | 100 | 1958 | 2058 | \$96,589 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$16.46 | 75 | 1958 | 2033 | \$106,061 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$11.07 | 30 | 1958 | 1988 | \$71,330 | 0% | 110% | \$78,463 |
| B2030 | Exterior Doors | \$0.94 | 30 | 1986 | 2016 | \$6,057 | 13% | 0.00% | \$0 |
| B3010105 | Built-Up | \$9.39 | 25 | 2001 | 2026 | \$60,505 | 56% | 0.00% | \$0 |
| C1010 | Partitions | \$6.78 | 40 | 1958 | 1998 | \$43,687 | - | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.45 | 40 | 1958 | 1998 | \$28,674 | 0% | 80.00% | \$22,939 |
| C1030 | Fittings | \$3.32 | 20 | 1986 | 2006 | \$21,393 | 0% | 110% | \$23,532 |
| C3010 | Wall Finishes | \$5.83 | 10 | 1986 | 1996 | \$37,566 | 0% | 110% | \$41,322 |
| C3020410 | Rubber/Resilient | \$12.14 | 15 | 1986 | 2001 | \$78,225 | 0% | 110% | \$86,047 |
| C3020410 | Sealed Concrete | \$1.27 | 15 | 1986 | 2001 | \$8,183 | 0% | 110% | \$9,002 |
| C3030105 | Plaster Ceilings | \$10.39 | 30 | 1986 | 2016 | \$66,948 | 13% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$8.31 | 30 | 1986 | 2016 | \$53,546 | 13% | 110% | \$58,900 |

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|--|------------|------|--------------|-------------------|-------------|------|--------|------------------|
| D2020 | Domestic Water Distribution | \$0.83 | 30 | 1958 | 1988 | \$5,348 | 0% | 110% | \$5,883 |
| D2030 | Sanitary Waste | \$2.83 | 30 | 1958 | 1988 | \$18,235 | 0% | 110% | \$20,059 |
| D2090 | Other Plumbing Systems- Nat Gas | \$0.78 | 20 | 1958 | 1978 | \$5,026 | 0% | 110% | \$5,529 |
| D3010 | Energy Supply | \$4.46 | 30 | 1958 | 1988 | \$28,738 | - | 0.00% | \$0 |
| D3040 | Distribution Systems | \$11.34 | 30 | 2004 | 2034 | \$73,070 | 73% | 0.00% | \$0 |
| D3050 | Terminal & Package Units | \$12.31 | 15 | 2004 | 2019 | \$79,320 | 47% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$3.12 | 15 | 2004 | 2019 | \$20,104 | 47% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.12 | 15 | 2010 | 2025 | \$773 | 87% | 0.00% | \$0 |
| D5010 | Electrical Service/Distribution | \$4.24 | 30 | 1986 | 2016 | \$27,321 | 13% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$20.39 | 30 | 1986 | 2016 | \$131,384 | 13% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$1.13 | 15 | 2004 | 2019 | \$7,281 | 47% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.41 | 10 | 2004 | 2014 | \$9,085 | 20% | 0.00% | \$0 |
| D5030910 | Security System, Camers, Access Control | \$0.74 | 15 | 2004 | 2019 | \$4,768 | 47% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.74 | 15 | 2004 | 2019 | \$4,768 | 47% | 0.00% | \$0 |
| D5030920 | Public Address / Clock System | \$0.74 | 15 | 2004 | 2019 | \$4,768 | 47% | 0.00% | \$0 |
| E2010 | Fixed Furnishings | \$3.05 | 20 | 1958 | 1978 | \$19,653 | 0% | 110% | \$21,618 |
| Total | | \$190.80 | | | | \$1,229,429 | 22% | 30.36% | \$373,294 |

Building Deficiency Priority

Deficiencies by Priority:




3 - Short Term Conditions (2-3 Years) \$373,294

Boys Weight Room Condition Budget: \$373,294

Final

Building Condition Deficiencies

Current deficiencies included systems that have reached or exceeded their design life or components of the systems that are in need of repair. Systems that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Expected Life'. The following chart includes all current deficiencies associated with this facility.



Boys Weight Room Condition Budget: \$373,294

Final

Building Condition Deficiencies Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 75-year service life. Based on the assessment, it is expected to expire in 2033 and is non-renewable.

Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Boys Weight Room
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Short Term Conditions (2-3 Years)
Notes: The exterior window system has exceeded its useful life and requires replacement.
Correction: Renew System
Qty: 1-Ea.
Condition Budget: \$78,463

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

System: B3010 - Roof Coverings

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.

System: B3010105 - Built-Up

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2001. It has a 25-year service life. Based on the assessment, it is expected to expire in 2026.

Recommendation: No action is required.

System: C1010 - Partitions


Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 40-year service life which expired in 1998 and is non-renewable.

Recommendation: The system should be replaced.

System: C1020 - Interior Doors

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 40-year service life which expired in 1998.

Recommendation: The system should be replaced.



Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The interior door system is beyond its useful life and requires replacement. The doors are showing signs of wear and the hardware is not compliant.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$22,939



System: C1030 - Fittings

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 20-year service life which expired in 2006.

Recommendation: The system should be replaced.

Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The locker system is beyond its useful life, damaged and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$23,532

System: C3010 - Wall Finishes

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 10-year service life which expired in 1996.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The paint is beyond useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$41,322

System: C3020 - Floor Finishes

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.



System: C3020410 - Rubber/Resilient

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 15-year service life which expired in 2001.

Recommendation: The system should be replaced.

Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The rubber flooring is showing signs of wear and some damage.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$86,047

System: C3020410 - Sealed Concrete

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 15-year service life which expired in 2001.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Boys Weight Room
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Short Term Conditions (2-3 Years)
Notes: The sealant on the concrete is failing and the concrete has been exposed.
Correction: Renew System
Qty: 1-Ea.
Condition Budget: \$9,002

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3030105 - Plaster Ceilings

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.



System: D2010 - Plumbing Fixtures

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 30-year service life. However, in the assessment, it was found to be currently deficient.

Recommendation: The system should be replaced.

Deficiency

Location: Boys Weight Room
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Short Term Conditions (2-3 Years)
Notes: The plumbing fixtures are failing. The showers do not work and the remaining plumbing fixtures are beyond their expected useful life. Recommend replacing the plumbing fixtures.
Correction: Renew System
Qty: 1-Ea.
Condition Budget: \$58,900

Final



System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The domestic water distribution system is beyond its expected service life and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$5,883



System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The sanitary waste system is failing. The drain in the shower is inoperable and the system should be replaced.

Correction: Renew System

Qty: 1-Ea.


Condition Budget: \$20,059

System: D2090 - Other Plumbing Systems-Nat Gas

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 20-year service life which expired in 1978.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The natural gas service is beyond it's expected service life and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$5,529

System: D3010 - Energy Supply

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988 and is non-renewable.

Recommendation: The system should be replaced.

System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 30-year service life. Based on the assessment, it is expected to expire in 2034.

Recommendation: No action is required.

System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 15-year service life. Based on the assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D5010 - Electrical Service/Distribution

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

System: D5020 - Lighting and Branch Wiring

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

System: D5030 - Communications and Security

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.

System: D5030310 - Telephone Systems

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D5030910 - Fire Alarm System

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 10-year service life. Based on the assessment, it is expected to expire in 2014.

Recommendation: No action is required.

System: D5030910 - Security System, Camers, Access Control

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D5030920 - LAN System

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D5030920 - Public Address / Clock System

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.



System: E2010 - Fixed Furnishings

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 20-year service life which expired in 1978.

Recommendation: The system should be replaced.

Deficiency

Location: Boys Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The benches in the locker area are beyond their useful life and require replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$21,618

Final

Building Name: Girls Weight Room

Year Built: 1958
Gross Area (SF): 1,964

The Yates High School Girl's Weight Room Building is a 1-story building. Originally built in 1958, there have been no additions with renovations in 1986. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|---------------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 0% | 46.38% | \$37,244 |
| B30 Roofing | 56% | 0.00% | \$0 |
| C10 Interior Construction | 0% | 49.56% | \$20,328 |
| C30 Interior Finishes | 0% | 110.00% | \$64,689 |
| D20 Plumbing | 0% | 110.00% | \$37,828 |
| D30 HVAC | 27% | 45.71% | \$38,148 |
| D40 Fire Protection | 26% | 0.00% | \$0 |
| D50 Electrical | 4% | 94.52% | \$76,413 |
| | | Total: | \$274,651 |


Building Deficiency Condition Budget Detail

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|---------------------------------|------------|------|--------------|-------------------|-------------|------|--------|------------------|
| A1010 | Standard Foundations | \$9.84 | 100 | 1958 | 2058 | \$26,090 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$8.50 | 100 | 1958 | 2058 | \$22,537 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$15.94 | 100 | 1958 | 2058 | \$42,263 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$17.52 | 75 | 1958 | 2033 | \$46,453 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$11.77 | 30 | 1958 | 1988 | \$31,207 | 0% | 110% | \$34,328 |
| B2030 | Exterior Doors | \$1.00 | 30 | 1958 | 1988 | \$2,651 | 0% | 110% | \$2,917 |
| B3010105 | Built-Up | \$9.58 | 25 | 2001 | 2026 | \$25,400 | 56% | 0.00% | \$0 |
| C1010 | Partitions | \$7.21 | 40 | 1958 | 1998 | \$19,117 | - | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.73 | 40 | 1986 | 2026 | \$12,541 | 35% | 80.00% | \$10,033 |
| C1030 | Fittings | \$3.53 | 20 | 1986 | 2006 | \$9,359 | 0% | 110% | \$10,295 |
| C3010 | Wall Finishes | \$6.21 | 10 | 1986 | 1996 | \$16,465 | 0% | 110% | \$18,112 |
| C3020410 | Rubber/Resilient | \$14.08 | 15 | 1986 | 2001 | \$37,332 | 0% | 110% | \$41,065 |
| C3020410 | VCT | \$1.89 | 15 | 1986 | 2001 | \$5,011 | 0% | 110% | \$5,512 |
| D2010 | Plumbing Fixtures | \$8.56 | 30 | 1958 | 1988 | \$22,696 | 0% | 110% | \$24,966 |
| D2020 | Domestic Water Distribution | \$0.88 | 30 | 1958 | 1988 | \$2,333 | 0% | 110% | \$2,567 |
| D2030 | Sanitary Waste | \$3.02 | 30 | 1958 | 1988 | \$8,007 | 0% | 110% | \$8,808 |
| D2040 | Rain Water Drainage | \$0.51 | 30 | 1958 | 1988 | \$1,352 | 0% | 110% | \$1,487 |
| D3040 | Distribution Systems | \$13.08 | 30 | 1958 | 1988 | \$34,680 | 0% | 110% | \$38,148 |
| D3050 | Terminal & Package Units | \$14.18 | 15 | 2004 | 2019 | \$37,597 | 47% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$4.22 | 15 | 2004 | 2019 | \$11,189 | 47% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.12 | 15 | 2010 | 2025 | \$318 | 87% | 0.00% | \$0 |
| D4090 | Other Fire Protection Systems | \$1.20 | 15 | 2000 | 2015 | \$3,182 | 20% | 0.00% | \$0 |
| D5010 | Electrical Service/Distribution | \$4.51 | 30 | 1958 | 1988 | \$11,958 | 0% | 110% | \$13,154 |
| D5020 | Lighting and Branch Wiring | \$21.69 | 30 | 1986 | 2016 | \$57,509 | 13% | 110% | \$63,260 |
| D5030310 | Telephone Systems | \$1.20 | 15 | 2004 | 2019 | \$3,182 | 47% | 0.00% | \$0 |

| Unifomat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|----------|---|------------|------|--------------|-------------------|-------------|------|--------|------------------|
| D5030910 | Fire Alarm System | \$1.51 | 10 | 2004 | 2014 | \$4,004 | 20% | 0.00% | \$0 |
| D5030910 | Security System, Camers, Access Control | \$0.79 | 15 | 2004 | 2019 | \$2,095 | 47% | 0.00% | \$0 |
| D5030920 | Public Address / Clock System | \$0.79 | 15 | 2004 | 2019 | \$2,095 | 47% | 0.00% | \$0 |
| Total | | \$188.06 | | | | \$498,622 | 16% | 55.08% | \$274,651 |

Building Deficiency Priority


Deficiencies by Priority:



Girls Weight Room Condition Budget: \$274,651

Final

Building Deficiencies Budget Detail



Girls Weight Room Condition Budget: \$274,652

Final

Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 75-year service life. Based on the assessment, it is expected to expire in 2033 and is non-renewable.


Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The exterior window system is beyond its useful life and requires replacement. The locks do not operate properly, and the frames are showing signs of wear.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$34,328



System: B2030 - Exterior Doors

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The exterior doors are showing signs of wear. The paint is peeling, the bottoms are rusting, as well as the hinges. The hardware is non-compliant.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$2,917

System: B3010 - Roof Coverings

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.

System: B3010105 - Built-Up

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2001. It has a 25-year service life. Based on the assessment, it is expected to expire in 2026.

Recommendation: No action is required.

Final

System: C1010 - Partitions

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 40-year service life which expired in 1998 and is non-renewable.

Recommendation: The system should be replaced.



System: C1020 - Interior Doors

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 40-year service life. However, in the assessment, it was found to be currently deficient.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The interior door system is beyond its useful life. The doors are showing signs of wear, and require replacement.

Correction: Renew System

Qty: 1-Ea.


Condition Budget: \$10,033

System: C1030 - Fittings

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 20-year service life which expired in 2006.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The tackboards and chalkboards are showing signs of wear and require replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$10,295



System: C3010 - Wall Finishes

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 10-year service life which expired in 1996.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The wall finishes are beyond useful life and require replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$18,112

System: C3020 - Floor Finishes

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.

System: C3020410 - Rubber/Resilient

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 15-year service life which expired in 2001.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The rubber flooring is beyond its useful life and requires replacement. Tiles are missing and damaged.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$41,065



System: C3020410 - VCT

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 15-year service life which expired in 2001.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The VCT flooring is showing signs of wear and requires replacement. Tiles are cracked, shifting missing.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$5,512

System: C3030 - Ceiling Finishes

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 20-year service life which expired in 2006.

Recommendation: The system should be replaced.

Final



System: D2010 - Plumbing Fixtures

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The original plumbing fixtures are stained, aged, and should be replaced with low flow fixtures.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$24,966



System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The domestic water system is galvanized steel, aged, and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$2,567

System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.



Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The sanitary sewer system is beyond its expected service life and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$8,808



System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The original rainwater drainage system is beyond its expected service life and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$1,487

System: D3040 - Distribution Systems

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Girls Weight Room

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The distribution system is aged, internally insulated, beyond its expected service life, and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$38,148

System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 15-year service life. Based on the assessment, it is expected to expire in 2025.

Recommendation: No action is required.

System: D4090 - Other Fire Protection Systems

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: D5010 - Electrical Service/Distribution

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.



Deficiency

Location: Girls Weight Room
 Distress: Beyond Expected Life
 Category: Deferred Maintenance
 Priority: 3 - Short Term Conditions (2-3 Years)
 Notes: The original service and distribution system is aged and should be replaced.
 Correction: Renew System
 Qty: 1-Ea.
 Condition Budget: \$13,154



System: D5020 - Lighting and Branch Wiring

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 30-year service life. However, in the assessment, it was found to be currently deficient.

Recommendation: The system should be replaced.

Deficiency

Location: Girls Weight Room
 Distress: Beyond Expected Life
 Category: Deferred Maintenance
 Priority: 3 - Short Term Conditions (2-3 Years)
 Notes: The lighting and branch wiring system is beyond it's expected service life, inefficient, and should be replaced.
 Correction: Renew System
 Qty: 1-Ea.
 Condition Budget: \$63,260

System: D5030 - Communications and Security

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.

System: D5030310 - Telephone Systems

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D5030910 - Fire Alarm System

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 10-year service life. Based on the assessment, it is expected to expire in 2014.

Recommendation: No action is required.

System: D5030910 - Security System, Camers, Access Control

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D5030920 - Public Address / Clock System

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

Final

Building Name: Greenhouse

Year Built: 1958
 Gross Area (SF): 2,400


The Greenhouse Building which has been abandoned, was originally built in 1958 and there have been no additions or renovations. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|--------------------------|------|---------------|------------------|
| F10 Special Construction | 0% | 110.00% | \$256,608 |
| | | Total: | \$256,608 |

Building Deficiency Condition Budget Detail


| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|----------------------|------------|------|--------------|-------------------|-------------|------|------|------------------|
| F10 | Special Construction | \$72.00 | 30 | 1958 | 1988 | \$233,280 | 0% | 110% | \$256,608 |
| Total | | \$72.00 | | | | \$233,280 | 0% | 110% | \$256,608 |

Building Deficiency Priority**Deficiencies by Priority:**

3 - Short Term Conditions (2-3 Years) \$256,608

Greenhouse Condition Budget: \$256,608

Building Deficiencies Budget Detail



Final

Building Deficiencies Budget Narrative

Final

Building Name: Main

Year Built: 1958
Gross Area (SF): 189,661

The Yates High School Main Building is a partial 3-story building and a partial 1-story building. Originally built in 1958, there have been additions in 1986, with renovations in 1986 and some minor renovations in 2001. The main building consists of classrooms, student dining, auditorium, two gyms and a pool. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|---------------|---------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| A20 Basement Construction | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 0% | 45.05% | \$2,639,029 |
| B30 Roofing | 53% | 0.00% | \$0 |
| C10 Interior Construction | 0% | 49.56% | \$1,513,722 |
| C20 Stairs | 12% | 0.00% | \$0 |
| C30 Interior Finishes | 18% | 50.29% | \$2,720,706 |
| D10 Conveying | 97% | 0.00% | \$0 |
| D20 Plumbing | 1% | 99.58% | \$2,771,402 |
| D30 HVAC | 28% | 39.47% | \$3,213,588 |
| D40 Fire Protection | 8% | 99.32% | \$261,931 |
| D50 Electrical | 12% | 20.71% | \$1,277,139 |
| E10 Equipment | 24% | 0.00% | \$0 |
| E20 Furnishings | 0% | 110.00% | \$704,116 |
| F10 Special Construction | 0% | 110.00% | \$943,516 |
| | | Total: | \$16,045,150 |


Building Deficiency Condition Budget Detail

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|----------------------|------------|------|--------------|-------------------|-------------|------|--------|------------------|
| A1010 | Standard Foundations | \$7.57 | 100 | 1958 | 2058 | \$1,938,241 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$6.55 | 100 | 1958 | 2058 | \$1,677,077 | - | 0.00% | \$0 |
| A2010 | Basement Excavation | \$0.23 | 100 | 1958 | 2058 | \$58,890 | - | 0.00% | \$0 |
| A2020 | Basement Walls | \$3.01 | 100 | 1958 | 2058 | \$770,687 | - | 0.00% | \$0 |
| B1010 | Floor Construction | \$16.27 | 100 | 1958 | 2058 | \$4,165,809 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$12.30 | 100 | 1958 | 2058 | \$3,149,321 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$13.51 | 75 | 1958 | 2033 | \$3,459,132 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$8.59 | 30 | 1958 | 1988 | \$2,199,404 | 0% | 110% | \$2,419,344 |
| B2030 | Exterior Doors | \$0.78 | 30 | 1958 | 1988 | \$199,713 | 0% | 110% | \$219,684 |
| B3010105 | Built-Up | \$7.40 | 25 | 2001 | 2026 | \$1,894,713 | 56% | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.51 | 30 | 1986 | 2016 | \$130,582 | 13% | 0.00% | \$0 |
| C1010 | Partitions | \$5.56 | 40 | 1958 | 1998 | \$1,423,595 | - | 0.00% | \$0 |
| C1020 | Interior Doors | \$3.65 | 40 | 1958 | 1998 | \$934,555 | 0% | 80.00% | \$747,644 |
| C1030 | Fittings | \$2.72 | 20 | 1958 | 1978 | \$696,435 | 0% | 110% | \$766,079 |
| C2010 | Stair Construction | \$3.26 | 40 | 1958 | 1998 | \$834,698 | 0% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$4.79 | 10 | 1986 | 1996 | \$1,226,443 | 0% | 110% | \$1,349,087 |
| C3020210 | Carpet | \$0.43 | 15 | 1986 | 2001 | \$110,098 | 0% | 110% | \$121,108 |
| C3020210 | Ceramic Tile | \$0.57 | 20 | 1958 | 1978 | \$145,944 | 0% | 110% | \$160,539 |
| C3020210 | Terrazzo | \$2.96 | 50 | 1958 | 2008 | \$757,885 | - | 0.00% | \$0 |
| C3020410 | VCT | \$2.52 | 15 | 1986 | 2001 | \$645,227 | 0% | 110% | \$709,749 |

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|--|------------|------|--------------|-------------------|--------------|------|--------|------------------|
| C3020410 | Wood | \$1.35 | 30 | 1958 | 1988 | \$345,657 | 0% | 110% | \$380,223 |
| C3030 | Ceiling Finishes | \$8.51 | 20 | 2001 | 2021 | \$2,178,920 | 45% | 0.00% | \$0 |
| D1010 | Elevators and Lifts | \$0.99 | 35 | 2011 | 2046 | \$253,482 | 97% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$6.82 | 30 | 1958 | 1988 | \$1,746,209 | 0% | 110% | \$1,920,830 |
| D2020 | Domestic Water Distribution | \$0.69 | 30 | 1958 | 1988 | \$176,669 | 0% | 110% | \$194,336 |
| D2030 | Sanitary Waste | \$2.33 | 30 | 1958 | 1988 | \$596,579 | 0% | 110% | \$656,237 |
| D2040 | Rain Water Drainage | \$0.39 | 30 | 1986 | 2016 | \$99,857 | 13% | 0.00% | \$0 |
| D2090 | Other Plumbing Systems- Nat Gas | \$0.64 | 20 | 1986 | 2006 | \$163,867 | 0% | 0.00% | \$0 |
| D3020 | Heat Generating Systems | \$3.53 | 30 | 1958 | 1988 | \$903,829 | 0% | 110% | \$994,212 |
| D3030 | Cooling Generating Systems | \$9.51 | 20 | 2001 | 2021 | \$2,434,963 | 45% | 0.00% | \$0 |
| D3040 | Distribution Systems | \$7.88 | 30 | 1986 | 2016 | \$2,017,614 | 13% | 110% | \$2,219,375 |
| D3050 | Terminal & Package Units | \$7.91 | 15 | 2004 | 2019 | \$2,025,295 | 47% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$2.30 | 15 | 2004 | 2019 | \$588,897 | 47% | 0.00% | \$0 |
| D3070 | Systems Testing & Balance | \$0.67 | 30 | 1986 | 2016 | \$171,548 | 13% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.10 | 15 | 2010 | 2025 | \$25,604 | 87% | 0.00% | \$0 |
| D4090 | Other Fire Protection Systems | \$0.93 | 15 | 1986 | 2001 | \$238,119 | 0% | 110% | \$261,931 |
| D5010 | Electrical Service/Distribution | \$3.48 | 30 | 1958 | 1988 | \$891,027 | 0% | 110% | \$980,130 |
| D5020 | Lighting and Branch Wiring | \$16.72 | 30 | 1986 | 2016 | \$4,281,028 | 13% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$0.93 | 15 | 2002 | 2017 | \$238,119 | 33% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.16 | 10 | 2002 | 2012 | \$297,009 | 0% | 100% | \$297,009 |
| D5030910 | Security System, Camers, Access Control | \$0.60 | 15 | 2002 | 2017 | \$153,625 | 33% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.60 | 15 | 2002 | 2017 | \$153,625 | 33% | 0.00% | \$0 |
| D5030920 | Public Address / Clock System | \$0.60 | 15 | 2002 | 2017 | \$153,625 | 33% | 0.00% | \$0 |
| E1020 | Institutional Equipment | \$1.35 | 20 | 1986 | 2006 | \$345,657 | 0% | 0.00% | \$0 |
| E1090 | Other Equipment | \$0.78 | 20 | 1986 | 2006 | \$199,713 | 0% | 0.00% | \$0 |
| E2010 | Fixed Furnishings | \$2.50 | 20 | 1958 | 1978 | \$640,106 | 0% | 110% | \$704,116 |
| F1040 | Special Facilities - Pool Area | \$3.35 | 20 | 1958 | 1978 | \$857,742 | 0% | 110% | \$943,516 |
| Total | | \$189.80 | | | | \$48,596,838 | 19% | 33.02% | \$16,045,150 |

Building Deficiency Priority


Deficiencies by Priority:



3 - Short Term Conditions (2-3 Years) \$16,045,150

Main Condition Budget: \$16,045,150

Building Deficiencies Budget Detail



Main Condition Budget: \$16,045,149

Final

Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: A2010 - Basement Excavation

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: A2020 - Basement Walls

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: B1010 - Floor Construction

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

Final

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 100-year service life. Based on the assessment, it is expected to expire in 2058 and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 75-year service life. Based on the assessment, it is expected to expire in 2033 and is non-renewable.

Recommendation: No action is required.



System: B2020 - Exterior Windows

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The exterior window system is beyond useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$2,419,344

System: B2030 - Exterior Doors

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Main
Distress: Beyond Expected Life
Category: Deferred Maintenance
Priority: 3 - Short Term Conditions (2-3 Years)
Notes: The exterior doors are showing signs of wear, beyond useful life and require replacement.
Correction: Renew System
Qty: 1-Ea.
Condition Budget: \$219,684

System: B3010 - Roof Coverings

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.

System: B3010105 - Built-Up

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2001. It has a 25-year service life. Based on the assessment, it is expected to expire in 2026.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 40-year service life which expired in 1998 and is non-renewable.

Recommendation: The system should be replaced.

System: C1020 - Interior Doors

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 40-year service life which expired in 1998.

Recommendation: The system should be replaced.



Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The interior doors are beyond useful life and require replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$747,644



System: C1030 - Fittings

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 20-year service life which expired in 1978.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The fittings throughout the building are beyond useful life and require replacement. This includes toilet partitions, lockers, room signage, chalk & tack boards throughout the building.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$766,079

System: C2010 - Stair Construction

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1958. It has a 40-year service life which expired in 1998. However, based on the 2009 assessment, the service life has been extended to 2017.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 10-year service life which expired in 1996.

Recommendation: The system should be replaced.



Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The wall finishes are beyond useful life and require replacement throughout.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$1,349,087

System: C3020 - Floor Finishes

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.



System: C3020210 - Carpet

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 15-year service life which expired in 2001.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The carpet system is beyond its useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$121,108

System: C3020210 - Ceramic Tile

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 20-year service life which expired in 1978.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Throughout the school the cermaic tile is showing signs of wear, is beyond its useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$160,539

System: C3020210 - Terrazzo

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 50-year service life which expired in 2008 and is non-renewable.

Recommendation: The system should be replaced.



System: C3020410 - VCT

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 15-year service life which expired in 2001.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The VCT system is showing signs of wear, cracked, shifting and/or delaminating throughout the building.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$709,749

Final



System: C3020410 - Wood

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The wood system in the gym and auditorium is beyond useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$380,223

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2001. It has a 20-year service life. Based on the assessment, it is expected to expire in 2021.

Recommendation: No action is required.

System: D1010 - Elevators and Lifts

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2011. It has a 35-year service life. Based on the assessment, it is expected to expire in 2046.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Main

Distress: Beyond Useful Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The plumbing fixtures are a mixture of original and replacement fixtures over the life of the building, are not low flow fixtures, are beyond their useful life, and should be replaced with low flow fixtures.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$1,920,830



System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The original domestic water distribution system is rusted, beyond its expected service life, and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$194,336

System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The original sanitary waste system is beyond its expected service life, rusted, has routine reported backups, and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$656,237

System: D2040 - Rain Water Drainage

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

System: D2090 - Other Plumbing Systems-Nat Gas

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 20-year service life which expired in 2006. However, based on the 2009 assessment, the service life has been extended to 2017.

Recommendation: No action is required.



System: D3020 - Heat Generating Systems

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The boiler is beyond its expected service life, inefficient, and should be replaced with an energy efficient model.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$994,212

Final

System: D3030 - Cooling Generating Systems

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2001. It has a 20-year service life. Based on the assessment, it is expected to expire in 2021.

Recommendation: No action is required.



System: D3040 - Distribution Systems

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 30-year service life. However, in the assessment, it was found to be currently deficient.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The distribution system piping and fan coil units are aged and showing rust, the piping insulation appears water logged, and the pipe sheathing is bent and damaged. The system should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$2,219,375

System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the assessment, it is expected to expire in 2019.

Recommendation: No action is required.

Final

System: D3070 - Systems Testing & Balance

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 15-year service life. Based on the assessment, it is expected to expire in 2025.

Recommendation: No action is required.



System: D4090 - Other Fire Protection Systems

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1986. It has a 15-year service life which expired in 2001.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The kitchen fire suppression system is beyond its expected service life and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$261,931

System: D5010 - Electrical Service/Distribution

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 30-year service life which expired in 1988.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The electrical service and distribution system is a combination of original service and switchboard and new service and switchboard. The system is assessed to be dependent upon it's oldest component, is beyond it's expected service life, and should be replaced.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$980,130

System: D5020 - Lighting and Branch Wiring

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 30-year service life. Based on the assessment, it is expected to expire in 2016.

Recommendation: No action is required.

System: D5030 - Communications and Security

Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date.

Recommendation: The system should be replaced.

System: D5030310 - Telephone Systems

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2002. It has a 15-year service life. Based on the assessment, it is expected to expire in 2017.

Recommendation: No action is required.

System: D5030910 - Fire Alarm System

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 2002. It has a 10-year service life. However, in the assessment, it was found to be currently deficient.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Main
 Distress: Beyond Expected Life
 Category: Deferred Maintenance
 Priority: 3 - Short Term Conditions (2-3 Years)
 Notes: The fire alarm system is operable but beyond its expected service life and should be replaced.
 Correction: Renew System
 Qty: 1-Ea.
 Condition Budget: \$297,009

System: D5030910 - Security System, Camers, Access Control

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2002. It has a 15-year service life. Based on the assessment, it is expected to expire in 2017.

Recommendation: No action is required.

System: D5030920 - LAN System

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2002. It has a 15-year service life. Based on the assessment, it is expected to expire in 2017.

Recommendation: No action is required.

System: D5030920 - Public Address / Clock System

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2002. It has a 15-year service life. Based on the assessment, it is expected to expire in 2017.

Recommendation: No action is required.

System: E1020 - Institutional Equipment

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 20-year service life which expired in 2006. However, based on the 2009 assessment, the service life has been extended to 2017.

Recommendation: No action is required.

System: E1090 - Other Equipment

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1986. It has a 20-year service life which expired in 2006. However, based on the 2009 assessment, the service life has been extended to 2017.

Recommendation: No action is required.



System: E2010 - Fixed Furnishings

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 20-year service life which expired in 1978.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The fixed casework and auditorium seating is beyond useful life and requires replacement.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$704,116



System: F1040 - Special Facilities - Pool Area

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1958. It has a 20-year service life which expired in 1978.

Recommendation: The system should be replaced.

Deficiency

Location: Main

Distress: Beyond Expected Life

Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: The pool area is beyond useful life and requires major renovations.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$943,516

Final

Appendix 1 - Assessment Criteria**Assessment Criteria**

| Task No | Task Description | Score | Comments |
|---------|---|-------|----------|
| 1000.00 | Facility Condition | | |
| 1000.00 | What is the Building's facility condition based on its facility condition index? | N/A | |
| 2000.00 | Educational Suitability | | |
| 2000.00 | What is the educational suitability score for this school as determined by MGT in 2012? | N/A | |
| 3000.00 | Technology Readiness | | |
| 3000.00 | What is the technology readiness score as determined by MGT in 2012? | N/A | |

Final

Glossary

| | |
|--|---|
| Abandoned Building | A facility owned by a district that is not occupied and not maintained. See Vacant. |
| Building | A fully enclosed and roofed structure that can be traversed internally without exiting to the exterior. |
| Building addition | An area, space or component of a building added to a building after the original building's year built date. "Main" is used to designate the original building. Additions built prior to 1980 were included in the Main building area calculations to reflect their predicted system depreciation characteristics and remaining useful life. |
| Calculated Next Renewal | Calculated Next Renewal refers to the year a system or building element completes its useful life based on its installed date and its expected useful or design life. |
| Capital Renewal | Capital Renewal refers to physical facility condition work (excluding suitability and technology work) that includes the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life that is not normally included in an annual operating maintenance budget. |
| Category | Category refers to the type or class of a user defined deficiency grouping with shared or similar characteristics. Category descriptions are: |
| Condition | Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use. |
| Condition Budget | The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work. |
| Condition Score | Condition Score is a factor used in the calculation of School Score expressed as |
| Correction | Correction refers to an assessor's recommended deficiency repair or replacement action. For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a material defined in a Unifomat II element, or system it is intended to address. It excludes other peripheral costs that may also be included in the packaging of repair, replacement or renewal improvements that may also be triggered by the deficiency correction. |
| Criteria | Criteria refers to the set of requirements, guidelines or standards that are assessed and rated to develop a score. |
| Current Period | The Current Period is the current year plus a user defined number of forward years. |
| Current Replacement Value (CRV) | Current Replacement Value (CRV), also known as Replacement Value represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to an optimal state-of-the-art condition under current codes and construction standards and techniques. |
| Deferred maintenance | Deferred maintenance is condition work (excluding suitability and technology readiness needs) deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available. |
| Deficiency | A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an intended purpose. |
| Distress | Distress refers to a user defined root cause of a deficiency. Distress descriptions are: |
| Element | Elements are the major components that comprise building systems as defined by Unifomat. |
| Extended Facility Condition Index (EFCI) | Extended Facility Condition Index (EFCI) is calculated as the condition needs for the current year plus facility system renewal for user defined forward years (the Current Period) divided by Current Replacement Value. |
| Facility | A facility refers to site(s), building(s), or building addition(s), or combinations thereof that provide a particular service or support of an educational purpose. |

Final

| | |
|-------------------------------------|--|
| Facility Condition Index (FCI) | FCI is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies to the facility's Current Replacement Value. It ranges from 0% (new) to 100%(very poor). |
| Forecast Period | The Forecast Period refers to a user defined number of years after the Current Period. |
| Gross square feet (GSF) | The area of the enclosed floor space of a building or building addition in square feet measured to the outside face of the enclosing wall. |
| Install year | The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced. |
| Life cycle | Life cycle refers to the period of time that a building or or element exists and can serve its intended function. The cycle includes warranty period, intrinsic period, and run to failure period. (See Useful Life) |
| Next Renewal | Next Renewal refers to a manually adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately current conditions. |
| Order of Magnitude | Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values. |
| Priority | Priority refers to a deficiency's urgency for repair as determined by the assessment team. |
| Remaining Service Life % | Remaining Service Life % is a calculated value such that $RSL\% = RSL \text{ divided by its system Design Life (not displayed)}$. |
| Remaining Service Life (RSL) | Remaining service life is a measure of a system's or element's predicted remaining useful life calculated as $RSL = \text{Next Renewal or Calculated Next Renewal Year minus the Current Year}$. |
| Remaining Service Life Index (RSLI) | The Remaining Service Life Index (RSLI) also known as the Condition Index (CI) is calculated as the sum of a renewable systems Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude softcost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life). |
| Remaining Service Life Value | Remaining Service Life Value also known as the RSL Weight is a calculated value used to determine the RSLI that is equal to the system Value (Unit Cost * Qty) * RSL (not displayed). |
| Replacement Value | See Current Replacement Value. |
| Site | A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility. |
| Soft Costs | Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user defined and include architectural, engineering, management, testing, and mitigation fees, and other owner pre- and post-construction expenses. |
| Suitability | Suitability refers to the measure of how well a facility supports the educational program(s) that it houses based on criteria derived from state laws, guidelines and national educational best practices. |
| Suitability Score | Suitability Score is a calculated value expressed as |
| System | System refers to building and related site work elements as described by ASTM Unifomat II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Unifomat II. |
| System Condition Index (SCI) | System Condition Index (SCI) is the ratio of a system's current condition deficiency costs to its replacement value - also known as "percent used" ranging from 0 percent to 100 percent or greater due to the addition of the system's renewal premium the additional costs to prepare for the system renewal such as demolition costs. |
| Technology Score | Technology Score, also known as Technology Readiness Score, is calculated as follows: (Sum of scoring for technology readiness criteria issues) * weighted value. |

Final

| | |
|---------------------------|--|
| Uniformat | Uniformat, also known as Uniformat II, a publication of the Construction Specification Institute (CSI), is ASTM Uniformat II Classification for Building Elements (E1557-97). UniFormat is a method of arranging construction information based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or assemblies. |
| Useful Life | Useful Life refers to the intrinsic period of time a system or element is expected to perform as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in this project are derived from the Building Owners and Managers (BOMA) organization's guidelines, RSMeans cost data, and from user defined historical experience. |
| Utilization | Utilization, also known as School Utilization, refers to ratio of students to the school's capacity calculated by dividing the number enrolled at the school by its Program Capacity. |
| Vacant | Vacant refers to a facility that is not occupied but is a maintained facility by a district. See Abandoned. |
| Weight (Weighting Factor) | Weight, also known as Weighting Factor, is a user defined factor used to apply more or less emphasis to system or element attributes such as deficiency category, deficiency priority or functional adequacy standard. For example, \$100 of a Priority 1 issue by default has the same cost value (1x) as \$100 of a Priority 5 item. Using weighting factors, the user can establish a priority factor so that for ranking or sorting purposes the facility (District, School, Building, Room, etc.) with a greater weighting (say 2x) thereby elevating it in rank order over the facility with Priority 1. |
| Year built | The year that a building or addition was originally built based on its date of substantial completion or occupancy. |

Final