School Assessment Report



Type: High Schools

School: Furr High School

Date: Jul 16, 2012

Final

Table of Contents

| Executive Summary | 4 |
|-----------------------------------------------|----|
| Condition Budget Summary | 4 |
| Educational Suitability Summary | 6 |
| Site | 7 |
| Site Summary | 7 |
| Deficiency Condition Budget Summary: Site | 8 |
| Site Deficiencies Budget Detail | 9 |
| Site Deficiency Priority | 9 |
| Site Condition Deficiencies | 10 |
| Site Deficiencies Budget Narrative | 11 |
| Buildings | 16 |
| Building: Auditorium Bld 8-B | 16 |
| Building Condition Budget Summary | 16 |
| Building Condition Budget Detail | 16 |
| Building Deficiency Priority | 17 |
| Building Condition Deficiencies | 18 |
| Building Condition Deficiencies Narrative | 19 |
| Building: Auxiliary Gymnasium building 1 G | 26 |
| Building Deficiency Condition Budget Summary | 26 |
| Building Deficiency Condition Budget Detail | 26 |
| Building Deficiency Priority | 27 |
| Building Deficiencies Budget Detail | 28 |
| Building Deficiencies Budget Narrative | 29 |
| Building: Central Plant Bldg 5 E | 36 |
| Building Deficiency Condition Budget Summary | 36 |
| Building Deficiency Condition Budget Detail | 36 |
| Building Deficiency Priority | 37 |
| Building Deficiencies Budget Detail | 38 |
| Building Deficiencies Budget Narrative | 39 |
| Building: Classroom / Laboratory Building 7 C | 43 |
| Building Deficiency Condition Budget Summary | 43 |
| Building Deficiency Condition Budget Detail | 43 |
| Building Deficiency Priority | 44 |
| Building Deficiencies Budget Detail | 45 |
| Building Deficiencies Budget Narrative | 46 |

| Building: Main building 4 A | 53 |
|-----------------------------------------|-----|
| Building Deficiency Priority | 54 |
| Building Deficiencies Budget Detail | 55 |
| Building Deficiencies Budget Narrative | 56 |
| Building: Main Gymnasium Bldg 2 H | 63 |
| Building Deficiency Priority | 64 |
| Building Deficiencies Budget Detail | 65 |
| Building Deficiencies Budget Narrative | 66 |
| Building: Reach Classrooms building 3 F | 72 |
| Building Deficiency Priority | 73 |
| Building Deficiencies Budget Detail | 74 |
| Building Deficiencies Budget Narrative | 75 |
| Building: Student Dining building 6 D | 82 |
| Building Deficiency Priority | 83 |
| Building Deficiencies Budget Detail | 84 |
| Building Deficiencies Budget Narrative | 85 |
| Building: Woodshop Building 09 I | 92 |
| Building Deficiency Priority | 93 |
| Building Deficiencies Budget Detail | 94 |
| Building Deficiencies Budget Narrative | 95 |
| Appendix 1 - Assessment Criteria | 101 |
| Glossary | 102 |



Executive Summary

School Name: Furr High School

| <u> </u> | |
|---------------------------------|--------------|
| Number of Buildings: | 9 |
| Gross Area (SF): | 147,458 |
| Replacement Value: | \$41,800,432 |
| Condition Budget: | \$3,532,550 |
| Total FCI: | 8.45% |
| Total RSLI: | 67% |
| Total CFI: | 8.5% |
| Condition Score: | 91.55 |
| Suitability, Educational Score: | 52.68 |
| Suitability, Tech Read Score: | 38.35 |
| Suitability, Total Score: | 49.81 |
| School Score: | 70.68 |



Summary:

Furr High School campus is located at 520 Mercury Dr. in Houston TX, and consists of 9 main school buildings. The original campus was constructed in 1960 and has no additions. Ancillary buildings on campus include, 2-gyms, T-Buildings, concession/press box, storage building, etc. In addition to the buildings, the campus contains covered walkways, baseball field, football field, track, etc. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for each building and other facilities on the campus.

Condition Budget Summary

Building condition is evaluated based on the functional elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a building cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this facility.


| 0.00% 0.00% 0.00% 0.14% 0.00% | \$0 \$0 \$0 \$7,096 |
|-------------------------------------------|-----------------------------------|
| 0.00% 0.14% | \$0 |
| 0.14% | |
| | \$7,096 |
| 0.00% | |
| 0.0070 | \$0 |
| 0.00% | \$0 |
| 0.00% | \$0 |
| 0.00% | \$0 |
| 0.00% | \$0 |
| 52.52% | \$1,711,301 |
| 5.35% | \$257,319 |
| 0.00% | \$0 |
| 0.00% | \$0 |
| 1.05% | \$4,880 |
| | \$176,789 |
| | 52.52% 5.35% 0.00% 0.00% |

| Uniformat Classification | RSLI | SCI | Condition Budget |
|-------------------------------|------|---------|------------------|
| G20 Site Improvements | 43% | 32.77% | \$902,775 |
| G30 Site Mechanical Utilities | 0% | 105.00% | \$472,389 |
| G40 Site Electrical Utilities | 96% | 0.00% | \$0 |
| | | Total: | \$3,532,550 |

Condition Deficiency Priority

| Building | | | Condition Budget | | | | | |
|-------------------------------------------|---------|-------|------------------|------------|-------------|------------|------------|-------------|
| /Site | GSF | FCI | Priority 1 | Priority 2 | Priority 3 | Priority 4 | Priority 5 | Total |
| Auditorium Bld 8-B | 11,263 | 8.3% | \$0 | \$0 | \$240,848 | \$0 | \$0 | \$240,848 |
| Auxiliary Gymnasium building 1 G | 12,905 | 13.7% | \$0 | \$0 | \$453,175 | \$0 | \$0 | \$453,175 |
| Central Plant Bldg 5 E | 1,261 | 1.6% | \$0 | \$0 | \$12,423 | \$0 | \$0 | \$12,423 |
| Classroom / Laboratory Building 7 C | 11,176 | 2.4% | \$0 | \$0 | \$67,713 | \$0 | \$0 | \$67,713 |
| Main building 4 A | 59,284 | 6.1% | \$0 | \$610,095 | \$318,693 | \$0 | \$0 | \$928,788 |
| Main Gymnasium Bldg 2 H | 18,095 | 5.7% | \$0 | \$0 | \$264,652 | \$0 | \$0 | \$264,652 |
| Reach Classrooms building 3 F | 10,094 | 2.3% | \$0 | \$0 | \$59,209 | \$0 | \$0 | \$59,209 |
| Site | | 38.9% | \$0 | \$0 | \$1,375,164 | \$0 | \$0 | \$1,375,164 |
| Student Dining building 6 D | 20,250 | 2.4% | \$0 | \$0 | \$125,698 | \$0 | \$0 | \$125,698 |
| Woodshop Building 09 I | 3,130 | 0.6% | \$0 | \$0 | \$4,880 | \$0 | \$0 | \$4,880 |
| Total: | 147,458 | 8.5% | \$0 | \$610,095 | \$2,922,455 | \$0 | \$0 | \$3,532,550 |





3 - Short Term Conditions (2-3 Years) \$2,922,455

School Condition Budget: \$3,532,550

Educational Suitability Summary

The MGT BASYS-generated document appended to this report provides information about the Educational Suitability of this school, based on the site visit using MGT's ESA guidelines. Each area was scored 5, 4, 3, 2, 1, or N/A with 1 being a high score. Items are scored N/A if they are not appropriate to that school program (e.g., football fields at an elementary school or preschool at a high school) or are not needed at a school. All scores are shown in the narrative supporting the score.



Site

Site Summary

Site condition is evaluated based on the functional elements of a site and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this facility.



 Site Acreage
 Total FCI:
 38.92%

 Replacement Value:
 \$3,533,462
 Total RSLI:
 42%

Site:

Furr High School original site was originally constructed in 1960. The site is occupied by 9 permanent structures and 14 temporary buildings. Campus site features include; paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, fencing, and practice fields, softball field, baseball field, and a soccer field. Site mechanical and electrical features include water, sewer, natural gas, and site lighting. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for the site features.

Final

Deficiency Condition Budget Summary: Site

Site condition is evaluated based on the functional elements of a site and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this site.

| Uniformat Classification | RSLI | SCI | Condition Budget |
|-------------------------------|------|---------|------------------|
| G20 Site Improvements | 43% | 32.77% | \$902,775 |
| G30 Site Mechanical Utilities | 0% | 105.00% | \$472,389 |
| G40 Site Electrical Utilities | 96% | 0.00% | \$0 |
| | | Total: | \$1,375,164 |




Site Deficiencies Budget Detail

Site condition is evaluated based on the functional elements of a site and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this site.

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|------------------------------|---------------|------|-----------------|----------------------|-------------|------|--------|---------------------|
| G2010 | Roadways | \$1.75 | 25 | 2010 | 2035 | \$348,370 | 92% | 0.00% | \$0 |
| G2020 | Parking Lots | \$2.50 | 25 | 2011 | 2036 | \$497,671 | 96% | 0.00% | \$0 |
| | Pedestrian Paving - | | | | | | | | |
| G2020 | sidewalks, etc | \$1.45 | 30 | 1960 | 1990 | \$288,649 | 0% | 110% | \$317,514 |
| G2040 | Baseball Field | \$0.36 | 30 | 2004 | 2034 | \$71,665 | 73% | 0.00% | \$0 |
| | Basketball / hard court play | | | | | | | | |
| G2040 | area | \$1.25 | 10 | 2004 | 2014 | \$248,835 | 20% | 0.00% | \$0 |
| G2040 | Canopy | \$1.95 | 30 | 1960 | 1990 | \$388,183 | 0% | 100% | \$388,183 |
| G2040 | Football Field Natural Turf | \$0.14 | 10 | 2004 | 2014 | \$27,870 | 20% | 0.00% | \$0 |
| G2040 | Site Development | \$1.15 | 30 | 1960 | 1990 | \$228,929 | 0% | 0.00% | \$0 |
| G2040 | Softball Field | \$0.36 | 10 | 2004 | 2014 | \$71,665 | 20% | 0.00% | \$0 |
| G2040 | Tennis Court (s) | \$0.90 | 10 | 1960 | 1970 | \$179,161 | 0% | 110% | \$197,078 |
| | Track Synthetic Surface - | | | | | | | | |
| G2040 | Resurface only | \$0.78 | 10 | 2011 | 2021 | \$155,273 | 90% | 0.00% | \$0 |
| G2050 | Landscaping | \$1.25 | 10 | 1998 | 2008 | \$248,835 | - | 0.00% | \$0 |
| G3010 | Water Supply | \$0.86 | 50 | 1960 | 2010 | \$171,199 | 0% | 105% | \$179,759 |
| G3020 | Sanitary Sewer | \$0.75 | 50 | 1960 | 2010 | \$149,301 | 0% | 105% | \$156,766 |
| G3030 | Storm Sewer | \$0.65 | 50 | 1960 | 2010 | \$129,394 | 0% | 105% | \$135,864 |
| G4020 | Site Lighting | \$1.65 | 30 | 2011 | 2041 | \$328,463 | 97% | 0.00% | \$0 |
| Total | | \$17.75 | | | | \$3,533,462 | 42% | 38.92% | \$1,375,164 |

Site Deficiency Priority


Site Deficiencies by Priority:



Site Condition Budget: \$1,375,164

Site Condition Deficiencies

Current deficiencies included systems that have reached or exceeded their design life or components of the systems that are in need of repair. Systems that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Expected Life'. The following chart includes all current deficiencies associated with this site.



Site Condition Budget: \$1,375,164



Site Deficiencies Budget Narrative

Current deficiencies included systems that have reached or exceeded their design life or components of the systems that are in need of repair. Systems that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Expected Life'. The following chart includes all current deficiencies associated with this site.

System: G2010 - Roadways

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2010. It has a 25-year service life. Based on the assessment, it is expected to expire in 2035.

Recommendation: No action is required.

System: G2020 - Parking Lots

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2011. It has a 25-year service life. Based on the assessment, it is expected to expire in 2036.

assessment, it is expected to expire in 203

Recommendation: No action is required.

System: G2020 - Pedestrian Paving - sidewalks, etc

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: pedestrian paving damaged and beyond expected

life

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$317,514

System: G2040 - Baseball Field

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 30-year service life. Based on the assessment, it is expected to expire in 2034.

Recommendation: No action is required.

Final



System: G2040 - Basketball / hard court play area

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2014.

Recommendation: No action is required.

System: G2040 - Canopy

Analysis: The system age is either beyond expected life or does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

> components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: canopy beyond useful life replace.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$388,183

System: G2040 - Football Field Natural Turf

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2014.

Recommendation: No action is required.

System: G2040 - Site Development

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 30-year service life which expired

in 1990. However, based on the 2009

assessment, the service life has been extended

to 2017.

Recommendation: No action is required.

System: G2040 - Softball Field

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 10-year service life. Based on the assessment, it is expected to expire in 2014.





System: G2040 - Tennis Court (s)

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 10-year service life

which expired in 1970.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Tennis Court is cracked, nets missing net supports

damaged. System is beyond useful life. Replace

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$197,078

System: G2040 - Track Synthetic Surface - Resurface only

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2011. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2021.

Recommendation: No action is required.

System: G2050 - Landscaping

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1998. It has a 10-year service life

which expired in 2008.

Recommendation: The system should be replaced.

System: G3010 - Water Supply

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1960. It has a 50-year service life

which expired in 2010.

Recommendation: The system should be replaced.







Location: Site

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Building water supply lines beyond useful life.

Replace

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$179,759

System: G3020 - Sanitary Sewer

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 50-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: underground sewer pipe beyond useful life replace.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$156,766

System: G3030 - Storm Sewer

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 50-year service life

which expired in 2010.

Recommendation: The system should be replaced.

Deficiency

Location: Site

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: storm sewer system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$135,864



System: G4020 - Site Lighting

Analysis: The system is in use and functioning with an estimated remaining service life as indicated in

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2011. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2041.



Buildings

Building Name: Auditorium Bld 8-B

Year Built: 1960 Gross Area (SF): 11,263

The Furr High School Auditorium Building is a 1-story building. Originally built in 1960, there have been no additions and renovations in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Condition Budget Summary

Building condition is evaluated based on the functional elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these elements is known as a building cost model. Models are developed for similar building types and function. Systems are evaluated based on their costs, design life, installation date and next renewal. Systems that are within their design life are further evaluated to identify current deficient conditions which may have a significant impact on the System's remaining service life. The system value is based on RS Means Commercial Cost Data. Following are the Systems detail for this facility.

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|---------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 44% | 0.00% | \$0 |
| B30 Roofing | 67% | 0.00% | \$0 |
| C10 Interior Construction | 73% | 0.00% | \$0 |
| C30 Interior Finishes | 100% | 0.00% | \$0 |
| D20 Plumbing | 66% | 36.60% | \$64,059 |
| D30 HVAC | 86% | 0.00% | \$0 |
| D40 Fire Protection | 100% | 0.00% | \$0 |
| D50 Electrical | 94% | 0.00% | \$0 |
| E20 Furnishings | 0% | 110.00% | \$176,789 |
| | | Total: | \$240,848 |


Building Condition Budget Detail

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|-----------------------------|---------------|------|-----------------|----------------------|-------------|------|-------|---------------------|
| A1010 | Standard Foundations | \$8.56 | 100 | 1960 | 2060 | \$130,155 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$7.38 | 100 | 1960 | 2060 | \$112,213 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$13.86 | 100 | 1960 | 2060 | \$210,742 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$15.21 | 75 | 1960 | 2035 | \$231,269 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$10.23 | 30 | 2012 | 2042 | \$155,548 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$0.88 | 30 | 2012 | 2042 | \$13,380 | 100% | 0.00% | \$0 |
| B3010120 | Single Ply Membrane | \$12.81 | 15 | 2007 | 2022 | \$194,777 | 67% | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.57 | 30 | 2007 | 2037 | \$8,667 | 83% | 0.00% | \$0 |
| C1010 | Partitions | \$6.27 | 100 | 1960 | 2060 | \$95,336 | 48% | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.11 | 40 | 2012 | 2052 | \$62,493 | 100% | 0.00% | \$0 |
| C1030 | Fittings | \$3.07 | 20 | 2012 | 2032 | \$46,680 | 100% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$5.40 | 10 | 2012 | 2022 | \$82,107 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$12.18 | 20 | 2012 | 2032 | \$185,198 | 100% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$9.60 | 20 | 2012 | 2032 | \$145,968 | 100% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$7.68 | 30 | 2012 | 2042 | \$116,775 | 100% | 0.00% | \$0 |
| D2020 | Domestic Water Distribution | \$0.76 | 30 | 1960 | 1990 | \$11,556 | 0% | 110% | \$12,711 |
| D2030 | Sanitary Waste | \$2.62 | 30 | 1960 | 1990 | \$39,837 | 0% | 110% | \$43,821 |
| D2040 | Rain Water Drainage | \$0.45 | 30 | 1960 | 1990 | \$6,842 | 0% | 110% | \$7,526 |

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|-----------------------------|---------------|------|-----------------|----------------------|-------------|---------|-------|---------------------|
| D3010 | Energy Supply | \$4.12 | 30 | 1960 | 1990 | \$62.645 | - INOLI | 0.00% | \$0 |
| D3040 | Distribution Systems | \$10.49 | 30 | 2012 | 2042 | \$159.501 | 100% | 0.00% | \$0 |
| D3050 | Terminal & Package Units | \$11.62 | 15 | 2012 | 2027 | \$176,683 | 100% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$2.58 | 15 | 2012 | 2027 | \$39,229 | 100% | 0.00% | \$0 |
| D3070 | Systems Testing & Balance | \$0.76 | 30 | 2012 | 2042 | \$11,556 | 100% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.10 | 15 | 2012 | 2027 | \$1,521 | 100% | 0.00% | \$0 |
| | Electrical | | | | | | | | |
| D5010 | Service/Distribution | \$3.92 | 30 | 2012 | 2042 | \$59,604 | 100% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$18.87 | 30 | 2012 | 2042 | \$286,919 | 100% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$1.05 | 15 | 2000 | 2015 | \$15,965 | 20% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.31 | 10 | 2012 | 2022 | \$19,919 | 100% | 0.00% | \$0 |
| | Security System, Camers, | | | | | | | | |
| D5030910 | Access Control | \$0.70 | 15 | 2009 | 2024 | \$10,644 | 80% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.70 | 15 | 2012 | 2027 | \$10,644 | 100% | 0.00% | \$0 |
| | Public Address / Clock | | | | | | | | |
| D5030920 | System | \$0.70 | 15 | 2000 | 2015 | \$10,644 | 20% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$0.89 | 20 | 2012 | 2032 | \$13,532 | 100% | 0.00% | \$0 |
| E2010 | Fixed Furnishings | \$10.57 | 20 | 1960 | 1980 | \$160,717 | 0% | 110% | \$176,789 |
| Total | | \$190.02 | | | | \$2,889,264 | 83% | 8.34% | \$240,848 |

Building Deficiency Priority

Deficiencies by Priority:




Auditorium Bld 8-B Condition Budget: \$240,848



Building Condition Deficiencies

Current deficiencies included systems that have reached or exceeded their design life or components of the systems that are in need of repair. Systems that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Expected Life'. The following chart includes all current deficiencies associated with this facility.



Auditorium Bld 8-B Condition Budget: \$240,847



Building Condition Deficiencies Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on

the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

is non-renewable.

Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

System: B3010 - Roof Coverings

Analysis: The system Warning: unknown next-renewal

year. The system was installed at an unknown

date.

Recommendation: The system should be replaced.

System: B3010120 - Single Ply Membrane

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2037.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on

the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2052.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the assessment, it is expected to expire in 2022.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Auditorium Bld 8-B
Distress: Beyond Expected Life
Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Domestic water distribution system beyond useful

life. Replace.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$12,711





System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Auditorium Bld 8-B
Distress: Beyond Expected Life
Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: sanitary waste system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$43,821

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Auditorium Bld 8-B
Distress: Beyond Expected Life
Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Rain water drainage system is damaged and

beyond useful life. replace

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$7,526

System: D3010 - Energy Supply

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life which expired in 1990 and is non-renewable.

Recommendation: The system should be replaced.



System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3070 - Systems Testing & Balance

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5010 - Electrical Service/Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

System: D5020 - Lighting and Branch Wiring Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5030 - Communications and Security Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: D5030310 - Telephone Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015. Recommendation: No action is required. System: D5030910 - Fire Alarm System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: D5030910 - Security System, Camers, Access Control Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2009. It has a 15-year service life. Based on the assessment, it is expected to expire in 2024. Recommendation: No action is required. System: D5030920 - LAN System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D5030920 - Public Address / Clock System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015. Recommendation: No action is required.

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E2010 - Fixed Furnishings

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 20-year service life

which expired in 1980.

Recommendation: The system should be replaced.

Deficiency

Location: Auditorium Bld 8-B
Distress: Beyond Expected Life
Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: seating damaged and/or beyond useful life

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$176,789

Final

Building Name: Auxiliary Gymnasium building 1 G

Year Built: 1960 Gross Area (SF): 12,905

The Furr High School Auxiliary Gymnasium Building is a 1-story building. Originally built in 1960, there have been no additions but the building has been renovation in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|--------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 42% | 0.00% | \$0 |
| B30 Roofing | 100% | 0.00% | \$0 |
| C10 Interior Construction | 62% | 0.00% | \$0 |
| C20 Stairs | 30% | 0.00% | \$0 |
| C30 Interior Finishes | 100% | 0.00% | \$0 |
| D20 Plumbing | 54% | 49.52% | \$195,855 |
| D30 HVAC | 43% | 48.19% | \$257,319 |
| D40 Fire Protection | 30% | 0.00% | \$0 |
| D50 Electrical | 100% | 0.00% | \$0 |
| E10 Equipment | 100% | 0.00% | \$0 |
| | | Total: | \$453,175 |


Building Deficiency Condition Budget Detail

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|-----------------------------|---------------|------|-----------------|----------------------|-------------|------|-------|---------------------|
| A1010 | Standard Foundations | \$12.47 | 100 | 1960 | 2060 | \$217.249 | - | 0.00% | \$0 |
| B1010 | Floor Construction | \$10.01 | 100 | 1960 | 2060 | \$174,392 | _ | 0.00% | \$0 |
| B1020 | Roof Construction | \$6.81 | 75 | 1960 | 2035 | \$118,642 | _ | 0.00% | \$0 |
| B2010 | Exterior Walls | \$12.47 | 75 | 1960 | 2035 | \$217,249 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$5.67 | 30 | 2012 | 2042 | \$98,781 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$3.41 | 30 | 2012 | 2042 | \$59,408 | 100% | 0.00% | \$0 |
| B3010 | Roof Coverings | \$8.78 | 20 | 2007 | 2027 | \$152,963 | - | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.26 | 30 | 2012 | 2042 | \$4,530 | 100% | 0.00% | \$0 |
| C1010 | Partitions | \$13.43 | 100 | 1960 | 2060 | \$233,974 | 48% | 0.00% | \$0 |
| C1030 | Fittings | \$5.30 | 30 | 2012 | 2042 | \$92,335 | 100% | 0.00% | \$0 |
| C2010 | Stair Construction | \$2.27 | 75 | 1960 | 2035 | \$39,547 | 31% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$6.81 | 20 | 2012 | 2032 | \$118,642 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$7.94 | 20 | 2012 | 2032 | \$138,329 | 100% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$5.67 | 20 | 2012 | 2032 | \$98,781 | 100% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$10.21 | 30 | 2012 | 2042 | \$177,876 | 100% | 0.00% | \$0 |
| D2020 | Domestic Water Distribution | \$4.54 | 30 | 1960 | 1990 | \$79,095 | 0% | 110% | \$87,004 |
| D2030 | Sanitary Waste | \$3.41 | 30 | 1960 | 1990 | \$59,408 | 0% | 110% | \$65,349 |
| D2040 | Rain Water Drainage | \$2.27 | 40 | 1960 | 2000 | \$39,547 | 0% | 110% | \$43,502 |
| D2090 | Other Plumbing Systems | \$2.27 | 30 | 2012 | 2042 | \$39,547 | 100% | 0.00% | \$0 |
| D3040 | Distribution Systems | \$15.88 | 20 | 2008 | 2028 | \$276,657 | 80% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$3.41 | 15 | 1960 | 1975 | \$59,408 | 0% | 100% | \$59,408 |
| D3070 | System Test & Balance | \$2.27 | 10 | 1960 | 1970 | \$39,547 | 0% | 100% | \$39,547 |
| D3090 | Other HVAC Systems/Equip | \$9.09 | 20 | 1960 | 1980 | \$158,364 | 0% | 100% | \$158,364 |
| D4030 | Fire Protection Specialties | \$0.20 | 10 | 2005 | 2015 | \$3,484 | 30% | 0.00% | \$0 |

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|----------------------------|---------------|------|-----------------|----------------------|-------------|------|--------|---------------------|
| | Electrical | | | | | | | | |
| D5010 | Service/Distribution | \$6.81 | 30 | 2012 | 2042 | \$118,642 | 100% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$22.27 | 30 | 2012 | 2042 | \$387,982 | 100% | 0.00% | \$0 |
| | Communications and | | | | | | | | |
| D5030 | Security | \$2.27 | 15 | 2012 | 2027 | \$39,547 | 100% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$2.27 | 20 | 2012 | 2032 | \$39,547 | 100% | 0.00% | \$0 |
| E1090 | Other Equipment | \$1.70 | 20 | 2012 | 2032 | \$29,617 | 100% | 0.00% | \$0 |
| Total | | \$190.17 | | | | \$3,313,094 | 73% | 13.68% | \$453,175 |

Building Deficiency Priority


Deficiencies by Priority:



Auxiliary Gymnasium building 1 G Condition Budget: \$453,175



Building Deficiencies Budget Detail



Auxiliary Gymnasium building 1 G Condition Budget: \$453,174



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1010 - Floor Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on

the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

is non-renewable.

Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

System: B3010 - Roof Coverings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: C2010 - Stair Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the

assessment, it is expected to expire in 2035.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Auxiliary Gymnasium building 1 G

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Domestic water distribution system beyond useful

life. Replace.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$87,004





System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Auxiliary Gymnasium building 1 G

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: sanitary waste system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$65,349

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 40-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency

Location: Auxiliary Gymnasium building 1 G

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: Rain water drainage system is damaged and

beyond useful life.

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$43,502

System: D2090 - Other Plumbing Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.



System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2008. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2028.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 15-year service life

which expired in 1975.

Recommendation: The system should be replaced.

Deficiency

Location: Auxiliary Gymnasium building 1 G

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$59,408

System: D3070 - System Test & Balance

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 10-year service life

which expired in 1970.

Recommendation: The system should be replaced.

Deficiency

Location: Auxiliary Gymnasium building 1 G

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Test and balance system beyond useful life.

rebalance

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$39,547







System: D3090 - Other HVAC Systems/Equip

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance

Guidelines for this system. The system was installed in 1960. It has a 20-year service life

which expired in 1980.

Recommendation: The system should be replaced.

Deficiency

Location: Auxiliary Gymnasium building 1 G

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: soft duct beyond expected life.

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$158,364

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2005. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: D5010 - Electrical Service/Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D5020 - Lighting and Branch Wiring

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: <u>D5030 - Communications and Security</u>

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E1090 - Other Equipment

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.



Building Name: Central Plant Bldg 5 E

Year Built: 1960 Gross Area (SF): 1,261

The Furr High School Central Plant Building is a 1-story building. Originally built in 1960, there have been no additions, with renovations in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|---------|------------------|
| B20 Exterior Enclosure | 4% | 11.44% | \$7,096 |
| B30 Roofing | 75% | 0.00% | \$0 |
| C10 Interior Construction | 94% | 0.00% | \$0 |
| C30 Interior Finishes | 73% | 0.00% | \$0 |
| D20 Plumbing | 0% | 105.00% | \$5,327 |
| D30 HVAC | 99% | 0.00% | \$0 |
| D50 Electrical | 99% | 0.00% | \$0 |
| | | Total: | \$12,423 |


Building Deficiency Condition Budget Detail

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|------------------------------------|---------------|------|-----------------|----------------------|-------------|------|-------|---------------------|
| A1010 | Standard Foundations | \$7.86 | 100 | 1960 | 2060 | \$13,380 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$15.92 | 100 | 1960 | 2060 | \$27,101 | _ | 0.00% | \$0 |
| B1020 | Roof Construction | \$15.84 | 100 | 1960 | 2060 | \$26,965 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$30.79 | 75 | 1960 | 2035 | \$52,415 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$3.97 | 30 | 1960 | 1990 | \$6,758 | 0% | 105% | \$7,096 |
| B2030 | Exterior Doors | \$1.67 | 30 | 2012 | 2042 | \$2,843 | 100% | 0.00% | \$0 |
| B3010 | Roof Coverings | \$14.26 | 20 | 2007 | 2027 | \$24,276 | 75% | 0.00% | \$0 |
| B3020 | Roof Openings | \$1.63 | 30 | 2007 | 2037 | \$2,775 | 83% | 0.00% | \$0 |
| C1010 | Partitions | \$1.01 | 100 | 1960 | 2060 | \$1,719 | 48% | 0.00% | \$0 |
| C1020 | Interior Doors | \$8.52 | 40 | 2012 | 2052 | \$14,504 | 100% | 0.00% | \$0 |
| C1030 | Fittings | \$0.71 | 20 | 2012 | 2032 | \$1,209 | 100% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$1.99 | 10 | 2012 | 2022 | \$3,388 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$2.05 | 100 | 1960 | 2060 | \$3,490 | 48% | 0.00% | \$0 |
| D2030 | Sanitary Waste | \$2.98 | 30 | 1960 | 1990 | \$5,073 | 0% | 105% | \$5,327 |
| D3030 | Cooling Generating Systems | \$113 | 30 | 2012 | 2042 | \$192,229 | 100% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$29.12 | 20 | 2012 | 2032 | \$49,572 | 100% | 0.00% | \$0 |
| D3090 | Other HVAC Systems/Equip | \$1.42 | 20 | 2012 | 2032 | \$2,417 | 100% | 0.00% | \$0 |
| D5010 | Electrical Service/Distribution | \$184 | 30 | 2012 | 2042 | \$312,568 | 100% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$6.99 | 30 | 2012 | 2042 | \$11,899 | 100% | 0.00% | \$0 |
| | Communications and | | | | | | | | |
| D5030 | Security | \$0.89 | 10 | 2005 | 2015 | \$1,515 | 30% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$3.75 | 20 | 2012 | 2032 | \$6,384 | 100% | 0.00% | \$0 |
| Total | | \$447.90 | | | | \$762,483 | 96% | 1.63% | \$12,423 |



Building Deficiency Priority


Deficiencies by Priority:



Central Plant Bldg 5 E Condition Budget: \$12,423



Building Deficiencies Budget Detail



Central Plant Bldg 5 E Condition Budget: \$12,423



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment it is expected to expire in 2060

the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

the assessment, it is expected to expire in and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

is non-renewable.

Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1960. It has a 30-year service life which expired in 1990.

Recommendation: The system should be replaced.

Final



Deficiency

Location: Central Plant Bldg 5 E Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: Louvers damaged and no longer functional.

Replace

Correction: Renew System

Qtv: 1-Ea. Condition Budget: \$7,096

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B3010 - Roof Coverings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2037.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on

the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2052.



System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Central Plant Bldg 5 E Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: sanitary waste system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$5,327

System: D3030 - Cooling Generating Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.



System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D3090 - Other HVAC Systems/Equip

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D5010 - Electrical Service/Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D5020 - Lighting and Branch Wiring

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: <u>D5030 - Communications and Security</u>

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2005. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2015.

Recommendation: No action is required.

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Building Name: Classroom / Laboratory Building 7 C

Year Built: 1960 Gross Area (SF): 11,176

The Furr High School Classroom/Laboratory Building is a 1-story building. Originally built in 1960, there have been no additions, with renovations in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|--------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 44% | 0.00% | \$0 |
| B30 Roofing | 68% | 0.00% | \$0 |
| C10 Interior Construction | 73% | 0.00% | \$0 |
| C30 Interior Finishes | 100% | 0.00% | \$0 |
| D20 Plumbing | 66% | 36.64% | \$67,713 |
| D30 HVAC | 100% | 0.00% | \$0 |
| D40 Fire Protection | 99% | 0.00% | \$0 |
| D50 Electrical | 96% | 0.00% | \$0 |
| E20 Furnishings | 100% | 0.00% | \$0 |
| | | Total: | \$67,713 |


Building Deficiency Condition Budget Detail

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|-----------------------------|---------|------|---------|-----------|-------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| A1010 | Standard Foundations | \$9.08 | 100 | 1960 | 2060 | \$136,995 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$7.84 | 100 | 1960 | 2060 | \$118,287 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$14.72 | 100 | 1960 | 2060 | \$222,089 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$16.17 | 75 | 1960 | 2035 | \$243,966 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$10.86 | 30 | 2012 | 2042 | \$163,851 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$0.93 | 30 | 2012 | 2042 | \$14,031 | 100% | 0.00% | \$0 |
| B3010120 | Single Ply Membrane | \$13.27 | 15 | 2007 | 2022 | \$200,212 | 67% | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.61 | 30 | 2012 | 2042 | \$9,203 | 100% | 0.00% | \$0 |
| C1010 | Partitions | \$6.66 | 100 | 1960 | 2060 | \$100,483 | 48% | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.37 | 40 | 2012 | 2052 | \$65,933 | 100% | 0.00% | \$0 |
| C1030 | Fittings | \$3.26 | 20 | 2012 | 2032 | \$49,186 | 100% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$5.74 | 10 | 2012 | 2022 | \$86,603 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$12.92 | 20 | 2012 | 2032 | \$194,932 | 100% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$10.19 | 20 | 2012 | 2032 | \$153,743 | 100% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$8.17 | 30 | 2012 | 2042 | \$123,266 | 100% | 0.00% | \$0 |
| D2020 | Domestic Water Distribution | \$0.82 | 30 | 1960 | 1990 | \$12,372 | 0% | 110% | \$13,609 |
| D2030 | Sanitary Waste | \$2.79 | 30 | 1960 | 1990 | \$42,094 | 0% | 110% | \$46,304 |
| D2040 | Rain Water Drainage | \$0.47 | 30 | 1960 | 1990 | \$7,091 | 0% | 110% | \$7,800 |
| D3040 | Distribution Systems | \$11.15 | 30 | 2012 | 2042 | \$168,227 | 100% | 0.00% | \$0 |
| D3050 | Terminal & Package Units | \$12.34 | 15 | 2012 | 2027 | \$186,181 | 100% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$2.75 | 15 | 2012 | 2027 | \$41,491 | 100% | 0.00% | \$0 |
| D3070 | Systems Testing & Balance | \$0.81 | 30 | 2012 | 2042 | \$12,221 | 100% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.11 | 15 | 2012 | 2027 | \$1,660 | 100% | 0.00% | \$0 |
| | Other Fire Protection | | | | | | | | |
| D4090 | Systems | \$1.11 | 15 | 2012 | 2027 | \$16,747 | 100% | 0.00% | \$0 |
| | Electrical | · | | | | , , | | | · |
| D5010 | Service/Distribution | \$4.16 | 30 | 2012 | 2042 | \$62,764 | 100% | 0.00% | \$0 |

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|----------------------------|----------|------|---------|-----------|-------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| D5020 | Lighting and Branch Wiring | \$20.04 | 30 | 2012 | 2042 | \$302,356 | 100% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$1.11 | 15 | 2000 | 2015 | \$16,747 | 20% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.39 | 10 | 2012 | 2022 | \$20,972 | 100% | 0.00% | \$0 |
| | Security System, Camers, | | | | | | | | |
| D5030910 | Access Control | \$0.73 | 15 | 2005 | 2020 | \$11,014 | 53% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.73 | 15 | 2012 | 2027 | \$11,014 | 100% | 0.00% | \$0 |
| | Public Address / Clock | | | | | | | | |
| D5030920 | System | \$0.73 | 15 | 2012 | 2027 | \$11,014 | 100% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$0.94 | 20 | 2012 | 2032 | \$14,182 | 100% | 0.00% | \$0 |
| E2010 | Fixed Furnishings | \$3.00 | 20 | 2012 | 2032 | \$45,263 | 100% | 0.00% | \$0 |
| Total | | \$189.97 | | | | \$2,866,191 | 91% | 2.36% | \$67,713 |

Building Deficiency Priority


Deficiencies by Priority:



Classroom / Laboratory Building 7 C Condition Budget: \$67,713



Building Deficiencies Budget Detail



Classroom / Laboratory Building 7 C Condition Budget: \$67,713



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

is non-renewable.

Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

System: B3010 - Roof Coverings

Analysis: The system Warning: unknown next-renewal

year. The system was installed at an unknown

date.

Recommendation: The system should be replaced.

System: B3010120 - Single Ply Membrane

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on

the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2052.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Classroom / Laboratory Building 7 C

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Domestic water distribution system beyond useful

life. Replace.

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$13,609





System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Classroom / Laboratory Building 7 C

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: sanitary waste system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$46,304

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Classroom / Laboratory Building 7 C

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: Rain water drainage system is damaged and

beyond useful life.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$7,800

System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.



System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3070 - Systems Testing & Balance

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D4090 - Other Fire Protection Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5010 - Electrical Service/Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

System: D5020 - Lighting and Branch Wiring Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5030 - Communications and Security Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: D5030310 - Telephone Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015. Recommendation: No action is required. System: D5030910 - Fire Alarm System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: D5030910 - Security System, Camers, Access Control Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2005. It has a 15-year service life. Based on the assessment, it is expected to expire in 2020. Recommendation: No action is required. System: D5030920 - LAN System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D5030920 - Public Address / Clock System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required.

FOR OFFICIAL USE ONLY

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E2010 - Fixed Furnishings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.



Building Name: Main building 4 A

Year Built: 1960 Gross Area (SF): 59,284

The Furr High School Main Building is a 3-story building, originally built in 1960. There have been no additions to the building. Renovations were completed in 2008, and a current 2012 project is underway. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|--------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 44% | 0.00% | \$0 |
| B30 Roofing | 52% | 0.00% | \$0 |
| C10 Interior Construction | 59% | 0.00% | \$0 |
| C20 Stairs | 10% | 0.00% | \$0 |
| C30 Interior Finishes | 100% | 0.00% | \$0 |
| D10 Conveying | 99% | 0.00% | \$0 |
| D20 Plumbing | 41% | 64.15% | \$928,788 |
| D30 HVAC | 81% | 0.00% | \$0 |
| D40 Fire Protection | 66% | 0.00% | \$0 |
| D50 Electrical | 97% | 0.00% | \$0 |
| E10 Equipment | 99% | 0.00% | \$0 |
| E20 Furnishings | 100% | 0.00% | \$0 |
| - | | Total: | \$928,788 |


Building Deficiency Condition Budget Detail

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|-----------------------------|---------|------|---------|-----------|-------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| A1010 | Standard Foundations | \$8.37 | 100 | 1960 | 2060 | \$669,880 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$7.23 | 100 | 1960 | 2060 | \$578,641 | - | 0.00% | \$0 |
| B1010 | Floor Construction | \$17.97 | 100 | 1960 | 2060 | \$1,438,200 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$13.57 | 100 | 1960 | 2060 | \$1,086,053 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$14.92 | 75 | 1960 | 2035 | \$1,194,098 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$10.03 | 30 | 2012 | 2042 | \$802,735 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$0.86 | 30 | 2012 | 2042 | \$68,829 | 100% | 0.00% | \$0 |
| B3010120 | Single Ply Membrane | \$3.47 | 15 | 2004 | 2019 | \$277,716 | 47% | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.57 | 30 | 2008 | 2038 | \$45,619 | 87% | 0.00% | \$0 |
| C1010 | Partitions | \$6.14 | 40 | 1960 | 2000 | \$491,405 | 0% | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.02 | 40 | 2012 | 2052 | \$321,734 | 100% | 0.00% | \$0 |
| C1030 | Fittings | \$3.00 | 20 | 2012 | 2032 | \$240,100 | 100% | 0.00% | \$0 |
| C2010 | Stair Construction | \$3.58 | 75 | 1960 | 2035 | \$286,520 | 31% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$5.28 | 10 | 2012 | 2022 | \$422,576 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$11.92 | 20 | 2012 | 2032 | \$953,998 | 100% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$9.40 | 20 | 2012 | 2032 | \$752,314 | 100% | 0.00% | \$0 |
| D1010 | Elevators and Lifts | \$3.02 | 35 | 2012 | 2047 | \$241,701 | 100% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$7.54 | 30 | 2012 | 2042 | \$603,452 | 100% | 0.00% | \$0 |
| D2020 | Domestic Water Distribution | \$3.19 | 30 | 1960 | 1990 | \$255,307 | 0% | 110% | \$280,837 |
| D2030 | Sanitary Waste | \$6.93 | 30 | 1960 | 1990 | \$554,631 | 0% | 110% | \$610,095 |
| D2040 | Rain Water Drainage | \$0.43 | 30 | 1960 | 1990 | \$34,414 | 0% | 110% | \$37,856 |
| D3040 | Distribution Systems | \$10.29 | 30 | 2008 | 2038 | \$823,544 | 87% | 0.00% | \$0 |
| D3050 | Terminal & Package Units | \$5.15 | 15 | 2006 | 2021 | \$412,172 | 60% | 0.00% | \$0 |

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|-----------------------------|----------|------|---------|-----------|--------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| D3060 | Controls & Instrumentation | \$2.53 | 15 | 2012 | 2027 | \$202,485 | 100% | 0.00% | \$0 |
| D3070 | Systems Testing & Balance | \$0.74 | 30 | 2012 | 2042 | \$59,225 | 100% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.10 | 15 | 2007 | 2022 | \$8,003 | 67% | 0.00% | \$0 |
| | Electrical | | | | | | | | |
| D5010 | Service/Distribution | \$3.85 | 30 | 2012 | 2042 | \$308,129 | 100% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$18.47 | 30 | 2012 | 2042 | \$1,478,217 | 100% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$1.03 | 15 | 2000 | 2015 | \$82,434 | 20% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.28 | 10 | 2012 | 2022 | \$102,443 | 100% | 0.00% | \$0 |
| | Security System, Camers, | | | | | | | | |
| D5030910 | Access Control | \$0.67 | 15 | 2012 | 2027 | \$53,622 | 100% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.67 | 15 | 2012 | 2027 | \$53,622 | 100% | 0.00% | \$0 |
| | Public Address / Clock | | | | | | | | |
| D5030920 | System | \$0.67 | 15 | 2012 | 2027 | \$53,622 | 100% | 0.00% | \$0 |
| E1020 | Institutional Equipment | \$0.34 | 20 | 2012 | 2032 | \$27,211 | 100% | 0.00% | \$0 |
| E2010 | Fixed Furnishings | \$2.75 | 20 | 2012 | 2032 | \$220,092 | 100% | 0.00% | \$0 |
| Total | | \$189.98 | | | | \$15,204,745 | 80% | 6.11% | \$928,788 |

Building Deficiency Priority


Deficiencies by Priority:



Main building 4 A Condition Budget: \$928,788



Building Deficiencies Budget Detail



Main building 4 A Condition Budget: \$928,788



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on

the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1010 - Floor Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the

assessment, it is expected to expire in 2035 and

is non-renewable.



System: B2020 - Exterior Windows

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B3010 - Roof Coverings

Analysis: The system Warning: unknown next-renewal

year. The system was installed at an unknown

date.

Recommendation: The system should be replaced.

System: B3010120 - Single Ply Membrane

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2004. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2019.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2008. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2038.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 40-year service life which expired

in 2000. However, based on the 2009

assessment, the service life has been extended

to 2020.



System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2052.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C2010 - Stair Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the

assessment, it is expected to expire in 2020.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

Final

System: D1010 - Elevators and Lifts

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 35-year service life. Based on the

assessment, it is expected to expire in 2047.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1960. It has a 30-year service life which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Main building 4 A
Distress: Beyond Expected Life
Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Domestic water distribution system beyond useful

life. Replace.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$280,837

System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.









Deficiency

Location: Main building 4 A Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 2 - Indirect Impact to Educational Mission (1 Year) Notes: SS is beyond expected service life, reported sewer

back up

Correction: Renew System

Qtv: 1-Ea. Condition Budget: \$610,095

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Main building 4 A Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: Rain water drainage system is damaged and

beyond useful life.

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$37,856

System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2008. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2038.

Recommendation: No action is required.

System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2006. It has a 15-year service life. Based on the assessment, it is expected to expire in 2021.

System: D3060 - Controls & Instrumentation Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D3070 - Systems Testing & Balance Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D4030 - Fire Protection Specialties Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 15-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: D5010 - Electrical Service/Distribution Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5020 - Lighting and Branch Wiring Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5030 - Communications and Security Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: D5030310 - Telephone Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015. Recommendation: No action is required.

System: D5030910 - Fire Alarm System

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: D5030910 - Security System, Camers, Access

<u>Control</u>

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5030920 - LAN System

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5030920 - Public Address / Clock System

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: E1020 - Institutional Equipment

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E2010 - Fixed Furnishings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.



Building Name: Main Gymnasium Bldg 2 H

Year Built: 1960 Gross Area (SF): 18,095

The Furr High School Main Gymnasium Building is a 1-story building. Originally built in 1960, there have been no additions, with renovations in started in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|--------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 42% | 0.00% | \$0 |
| B30 Roofing | 100% | 0.00% | \$0 |
| C10 Interior Construction | 61% | 0.00% | \$0 |
| C30 Interior Finishes | 100% | 0.00% | \$0 |
| D20 Plumbing | 49% | 56.96% | \$264,652 |
| D30 HVAC | 90% | 0.00% | \$0 |
| D40 Fire Protection | 100% | 0.00% | \$0 |
| D50 Electrical | 96% | 0.00% | \$0 |
| E10 Equipment | 100% | 0.00% | \$0 |
| | | Total: | \$264,652 |


Building Deficiency Condition Budget Detail

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|-----------------------------|---------|------|---------|-----------|-------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| A1010 | Standard Foundations | \$11.62 | 100 | 1960 | 2060 | \$283,856 | - | 0.00% | \$0 |
| B1010 | Floor Construction | \$9.51 | 100 | 1960 | 2060 | \$232,313 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$6.34 | 75 | 1960 | 2035 | \$154,875 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$11.62 | 75 | 1960 | 2035 | \$283,856 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$5.28 | 30 | 2012 | 2042 | \$128,981 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$3.17 | 30 | 2012 | 2042 | \$77,438 | 100% | 0.00% | \$0 |
| B3010 | Roof Coverings | \$8.18 | 20 | 2007 | 2027 | \$199,823 | - | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.23 | 30 | 2012 | 2042 | \$5,618 | 100% | 0.00% | \$0 |
| C1010 | Partitions | \$14.09 | 100 | 1960 | 2060 | \$344,194 | 48% | 0.00% | \$0 |
| C1030 | Fittings | \$4.93 | 30 | 2012 | 2042 | \$120,431 | 100% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$6.34 | 20 | 2012 | 2032 | \$154,875 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$7.39 | 20 | 2012 | 2032 | \$180,525 | 100% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$5.28 | 20 | 2012 | 2032 | \$128,981 | 100% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$9.51 | 30 | 2012 | 2042 | \$232,313 | 100% | 3.92% | \$9,108 |
| D2020 | Domestic Water Distribution | \$4.23 | 30 | 1960 | 1990 | \$103,331 | 0% | 110% | \$113,665 |
| D2030 | Sanitary Waste | \$3.17 | 30 | 1960 | 1990 | \$77,438 | 0% | 110% | \$85,181 |
| D2040 | Rain Water Drainage | \$2.11 | 40 | 1960 | 2000 | \$51,544 | 0% | 110% | \$56,698 |
| D3020 | Heat Generating Systems | \$3.28 | 30 | 2012 | 2042 | \$80,125 | 100% | 0.00% | \$0 |
| D3040 | Distribution Systems | \$14.80 | 20 | 2008 | 2028 | \$361,538 | 80% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$3.17 | 15 | 2012 | 2027 | \$77,438 | 100% | 0.00% | \$0 |
| D3070 | System Test & Balance | \$2.11 | 10 | 2012 | 2022 | \$51,544 | 100% | 0.00% | \$0 |
| D3090 | Other HVAC Systems/Equip | \$8.46 | 20 | 2012 | 2032 | \$206,663 | 100% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.19 | 10 | 2012 | 2022 | \$4,641 | 100% | 0.00% | \$0 |
| | Electrical | | | | | | | | • |
| D5010 | Service/Distribution | \$6.34 | 30 | 2012 | 2042 | \$154,875 | 100% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$20.74 | 30 | 2012 | 2042 | \$506.642 | 100% | 0.00% | \$0 |

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|--------------------------|---------------|------|-----------------|----------------------|-------------|------|-------|---------------------|
| | Communications and | | | | | | | | |
| D5030 | Security | \$2.11 | 15 | 2005 | 2020 | \$51,544 | 53% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$2.11 | 20 | 2012 | 2032 | \$51,544 | 100% | 0.00% | \$0 |
| E1020 | Institutional Equipment | \$13.74 | 30 | 2012 | 2042 | \$335,644 | 100% | 0.00% | \$0 |
| Total | | \$190.05 | | | | \$4,642,589 | 85% | 5.70% | \$264,652 |

Building Deficiency Priority


Deficiencies by Priority:



Main Gymnasium Bldg 2 H Condition Budget: \$264,652



Building Deficiencies Budget Detail



Main Gymnasium Bldg 2 H Condition Budget: \$264,652



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1010 - Floor Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment it is expected to expire in 2060

the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

assessment, it is expected to expire in 2035 and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

is non-renewable.

Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

System: B3010 - Roof Coverings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.



System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. However, in the assessment, it was found to be currently

deficient.

Recommendation: The system should be replaced.

Deficiency

Location: Main Gymnasium Bldg 2 H

Material: Plumbing Fixtures
Distress: Beyond Useful Life
Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Janitors Sinks are beyond useful life and need to

be replaced. Sinks are located at two locations in

the first floor.

Correction: Replace Custodial sinks

Qty: 2-Ea. Condition Budget: \$9,108

System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Main Gymnasium Bldg 2 H
Distress: Beyond Expected Life
Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Domestic water distribution system beyond useful

life. Replace.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$113,665









System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Main Gymnasium Bldg 2 H Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: sanitary waste system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$85,181

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 40-year service life

which expired in 2000.

Recommendation: The system should be replaced.

Deficiency

Location: Main Gymnasium Bldg 2 H Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: Rain water drainage system is damaged and

beyond useful life.

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$56,698

System: D3020 - Heat Generating Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.



System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2008. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2028.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3070 - System Test & Balance

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: D3090 - Other HVAC Systems/Equip

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: D5010 - Electrical Service/Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

System: D5020 - Lighting and Branch Wiring

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D5030 - Communications and Security

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2005. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2020.

Recommendation: No action is required.

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E1020 - Institutional Equipment

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.



Building Name: Reach Classrooms building 3 F

Year Built: 1960 Gross Area (SF): 10,094

The Furr High School reach Classroom Building is a 1-story building. Originally built in 1960, there have been no additions, with renovations beginning in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|--------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| A20 Basement Construction | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 44% | 0.00% | \$0 |
| B30 Roofing | 68% | 0.00% | \$0 |
| C10 Interior Construction | 73% | 0.00% | \$0 |
| C30 Interior Finishes | 100% | 0.00% | \$0 |
| D20 Plumbing | 66% | 36.60% | \$59,209 |
| D30 HVAC | 99% | 0.00% | \$0 |
| D40 Fire Protection | 27% | 0.00% | \$0 |
| D50 Electrical | 96% | 0.00% | \$0 |
| E10 Equipment | 99% | 0.00% | \$0 |
| E20 Furnishings | 99% | 0.00% | \$0 |
| | | Total: | \$59,209 |


Building Deficiency Condition Budget Detail

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|-----------------------------|---------|------|---------|-----------|-------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| A1010 | Standard Foundations | \$8.81 | 100 | 1960 | 2060 | \$120,053 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$7.61 | 100 | 1960 | 2060 | \$103,701 | - | 0.00% | \$0 |
| A2010 | Basement Excavation | \$0.24 | 100 | 1960 | 2060 | \$3,270 | - | 0.00% | \$0 |
| A2020 | Basement Walls | \$3.49 | 100 | 1960 | 2060 | \$47,558 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$14.28 | 100 | 1960 | 2060 | \$194,592 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$15.68 | 75 | 1960 | 2035 | \$213,670 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$10.53 | 30 | 2012 | 2042 | \$143,491 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$0.91 | 30 | 2012 | 2042 | \$12,400 | 100% | 0.00% | \$0 |
| B3010120 | Single Ply Membrane | \$13.56 | 15 | 2007 | 2022 | \$184,781 | 67% | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.59 | 30 | 2012 | 2042 | \$8,040 | 100% | 0.00% | \$0 |
| C1010 | Partitions | \$6.45 | 100 | 1960 | 2060 | \$87,894 | 48% | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.23 | 40 | 2012 | 2052 | \$57,642 | 100% | 0.00% | \$0 |
| C1030 | Fittings | \$3.15 | 20 | 2012 | 2032 | \$42,925 | 100% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$5.56 | 10 | 2012 | 2022 | \$75,766 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$12.54 | 20 | 2012 | 2032 | \$170,881 | 100% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$9.89 | 20 | 2012 | 2032 | \$134,770 | 100% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$7.92 | 30 | 2012 | 2042 | \$107,925 | 100% | 0.00% | \$0 |
| D2020 | Domestic Water Distribution | \$0.79 | 30 | 1960 | 1990 | \$10,765 | 0% | 110% | \$11,842 |
| D2030 | Sanitary Waste | \$2.71 | 30 | 1960 | 1990 | \$36,929 | 0% | 110% | \$40,622 |
| D2040 | Rain Water Drainage | \$0.45 | 30 | 1960 | 1990 | \$6,132 | 0% | 110% | \$6,745 |
| D3040 | Distribution Systems | \$10.81 | 30 | 2012 | 2042 | \$147,307 | 100% | 0.00% | \$0 |
| D3050 | Terminal & Package Units | \$11.97 | 15 | 2012 | 2027 | \$163,114 | 100% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$2.66 | 15 | 2012 | 2027 | \$36,248 | 100% | 0.00% | \$0 |
| D3070 | Systems Testing & Balance | \$0.78 | 30 | 2012 | 2042 | \$10,629 | 100% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.11 | 15 | 2012 | 2027 | \$1,499 | 100% | 0.00% | \$0 |

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|----------------------------|---------------|------|-----------------|----------------------|-------------|------|-------|---------------------|
| | Other Fire Protection | | | | | | | | |
| D4090 | Systems | \$1.07 | 15 | 2000 | 2015 | \$14,581 | 20% | 0.00% | \$0 |
| | Electrical | | | | | | | | |
| D5010 | Service/Distribution | \$4.04 | 30 | 2012 | 2042 | \$55,053 | 100% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$19.42 | 30 | 2012 | 2042 | \$264,634 | 100% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$1.07 | 15 | 2000 | 2015 | \$14,581 | 20% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.35 | 10 | 2012 | 2022 | \$18,396 | 100% | 0.00% | \$0 |
| | Security System, Camers, | | | | | | | | |
| D5030910 | Access Control | \$0.70 | 15 | 2005 | 2020 | \$9,539 | 53% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.70 | 15 | 2012 | 2027 | \$9,539 | 100% | 0.00% | \$0 |
| | Public Address / Clock | | | | | | | | |
| D5030920 | System | \$0.70 | 15 | 2012 | 2027 | \$9,539 | 100% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$0.91 | 20 | 2012 | 2032 | \$12,400 | 100% | 0.00% | \$0 |
| E1020 | Institutional Equipment | \$1.57 | 20 | 2012 | 2032 | \$21,394 | 100% | 0.00% | \$0 |
| E2010 | Fixed Furnishings | \$2.92 | 20 | 2012 | 2032 | \$39,791 | 100% | 0.00% | \$0 |
| Total | | \$190.17 | | | | \$2,591,428 | 90% | 2.28% | \$59,209 |

Building Deficiency Priority


Deficiencies by Priority:



Reach Classrooms building 3 F Condition Budget: \$59,209



Building Deficiencies Budget Detail



Reach Classrooms building 3 F Condition Budget: \$59,209



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment it is expected to expire in 2060

the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A2010 - Basement Excavation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

the assessment, it is expected to expire in 2060 and is non-renewable.

Recommendation: No action is required.

System: A2020 - Basement Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

Final

School Assessment Report - High Schools, Furr High School, Reach Classrooms building 3 F System: B2010 - Exterior Walls Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and is non-renewable. Recommendation: No action is required. System: B2020 - Exterior Windows Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: B2030 - Exterior Doors Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: B3010 - Roof Coverings Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: B3010120 - Single Ply Membrane Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 15-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: B3020 - Roof Openings Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement

Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060.

System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2052.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.



System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance

components, or in order to meet the performanc Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Reach Classrooms building 3 F

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Domestic water distribution system beyond useful

life. Replace.

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$11,842

System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Reach Classrooms building 3 F

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: sanitary waste system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$40,622

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.





Deficiency

Location: Reach Classrooms building 3 F

Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: Rain water drainage system is damaged and

beyond useful life.

Correction: Renew System

Qtv: 1-Ea. Condition Budget: \$6,745

System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3070 - Systems Testing & Balance

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

System: D4090 - Other Fire Protection Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015. Recommendation: No action is required. System: D5010 - Electrical Service/Distribution Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5020 - Lighting and Branch Wiring Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5030 - Communications and Security Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: D5030310 - Telephone Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2000. It has a 15-year service life. Based on the assessment, it is expected to expire in 2015. Recommendation: No action is required. System: D5030910 - Fire Alarm System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: D5030910 - Security System, Camers, Access Control Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2005. It has a 15-year service life. Based on the assessment, it is expected to expire in 2020. Recommendation: No action is required.

System: D5030920 - LAN System

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5030920 - Public Address / Clock System

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E1020 - Institutional Equipment

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E2010 - Fixed Furnishings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.



Building Name: Student Dining building 6 D

Year Built: 1960 Gross Area (SF): 20,250

The Furr High School Student Dining Building is a 1-story building. Originally built in 1960, there have been no additions, with renovations that began in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|--------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| A20 Basement Construction | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 44% | 0.00% | \$0 |
| B30 Roofing | 68% | 0.00% | \$0 |
| C10 Interior Construction | 72% | 0.00% | \$0 |
| C30 Interior Finishes | 100% | 0.00% | \$0 |
| D20 Plumbing | 68% | 34.44% | \$125,698 |
| D30 HVAC | 89% | 0.00% | \$0 |
| D40 Fire Protection | 100% | 0.00% | \$0 |
| D50 Electrical | 97% | 0.00% | \$0 |
| E10 Equipment | 99% | 0.00% | \$0 |
| E20 Furnishings | 100% | 0.00% | \$0 |
| | | Total: | \$125,698 |


Building Deficiency Condition Budget Detail

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|-----------------------------|---------------|------|-----------------|----------------------|-------------|---------|-------|---------------------|
| A1010 | Standard Foundations | \$9.32 | 100 | 1960 | 2060 | \$254,786 | - INOLI | 0.00% | \$0 |
| A1030 | Slab on Grade | \$8.06 | 100 | 1960 | 2060 | \$220,340 | - | 0.00% | \$0 |
| A2010 | Basement Excavation | \$0.26 | 100 | 1960 | 2060 | \$7.108 | - | 0.00% | \$0 |
| A2020 | Basement Walls | \$3.70 | 100 | 1960 | 2060 | \$101,149 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$15.12 | 100 | 1960 | 2060 | \$413,343 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$16.61 | 75 | 1960 | 2035 | \$454,076 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$11.16 | 30 | 2012 | 2042 | \$305,087 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$0.95 | 30 | 2012 | 2042 | \$25,971 | 100% | 0.00% | \$0 |
| B3010120 | Single Ply Membrane | \$14.36 | 15 | 2007 | 2022 | \$392,567 | 67% | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.63 | 30 | 2012 | 2042 | \$17,223 | 100% | 0.00% | \$0 |
| C1010 | Partitions | \$7.31 | 100 | 1960 | 2060 | \$199,837 | 48% | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.48 | 40 | 2012 | 2052 | \$122,472 | 100% | 0.00% | \$0 |
| C1030 | Fittings | \$3.35 | 20 | 2012 | 2032 | \$91,581 | 100% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$5.90 | 10 | 2012 | 2022 | \$161,291 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$13.27 | 20 | 2012 | 2032 | \$362,769 | 100% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$10.47 | 20 | 2012 | 2032 | \$286,224 | 100% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$8.39 | 30 | 2012 | 2042 | \$229,362 | 100% | 0.00% | \$0 |
| D2020 | Domestic Water Distribution | \$0.84 | 30 | 1960 | 1990 | \$22,964 | 0% | 110% | \$25,260 |
| D2030 | Sanitary Waste | \$2.86 | 30 | 1960 | 1990 | \$78,185 | 0% | 110% | \$86,004 |
| D2040 | Rain Water Drainage | \$0.48 | 30 | 1960 | 1990 | \$13,122 | 0% | 110% | \$14,434 |
| | Other Plumbing Systems- | | | | | | | | |
| D2090 | Nat Gas | \$0.78 | 20 | 2012 | 2032 | \$21,323 | 100% | 0.00% | \$0 |
| D3040 | Distribution Systems | \$11.44 | 30 | 2008 | 2038 | \$312,741 | 87% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$2.82 | 15 | 2012 | 2027 | \$77,092 | 100% | 0.00% | \$0 |
| D3070 | Systems Testing & Balance | \$0.82 | 30 | 2012 | 2042 | \$22,417 | 100% | 0.00% | \$0 |

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|-----------------------------|----------|------|---------|-----------|-------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| D4030 | Fire Protection Specialties | \$0.11 | 15 | 2012 | 2027 | \$3,007 | 100% | 0.00% | \$0 |
| | Other Fire Protection | | | | | | | | |
| D4090 | Systems | \$1.14 | 15 | 2012 | 2027 | \$31,165 | 100% | 0.00% | \$0 |
| | Electrical | | | | | | | | |
| D5010 | Service/Distribution | \$4.28 | 30 | 2012 | 2042 | \$117,005 | 100% | 0.00% | \$0 |
| D5020 | Lighting and Branch Wiring | \$20.57 | 30 | 2012 | 2042 | \$562,332 | 100% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$1.14 | 15 | 2005 | 2020 | \$31,165 | 53% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.43 | 10 | 2012 | 2022 | \$39,093 | 100% | 0.00% | \$0 |
| | Security System, Camers, | | | | | | | | |
| D5030910 | Access Control | \$0.75 | 15 | 2005 | 2020 | \$20,503 | 53% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.75 | 15 | 2012 | 2027 | \$20,503 | 100% | 0.00% | \$0 |
| | Public Address / Clock | | | | | | | | |
| D5030920 | System | \$0.75 | 15 | 2012 | 2027 | \$20,503 | 100% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$0.97 | 20 | 2012 | 2032 | \$26,517 | 100% | 0.00% | \$0 |
| E1020 | Institutional Equipment | \$1.66 | 20 | 2012 | 2032 | \$45,380 | 100% | 0.00% | \$0 |
| E2010 | Fixed Furnishings | \$3.08 | 20 | 2012 | 2032 | \$84,200 | 100% | 0.00% | \$0 |
| Total | | \$190.01 | | | | \$5,194,398 | 89% | 2.42% | \$125,698 |

Building Deficiency Priority


Deficiencies by Priority:



Student Dining building 6 D Condition Budget: \$125,698



Building Deficiencies Budget Detail



Student Dining building 6 D Condition Budget: \$125,698



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on

the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A2010 - Basement Excavation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A2020 - Basement Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

School Assessment Report - High Schools, Furr High School, Student Dining building 6 D System: B2010 - Exterior Walls Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and is non-renewable. Recommendation: No action is required. System: B2020 - Exterior Windows Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: B2030 - Exterior Doors Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: B3010 - Roof Coverings Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: B3010120 - Single Ply Membrane Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 15-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: B3020 - Roof Openings Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060.

System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2052.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

Recommendation: No action is required.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.



System: D2020 - Domestic Water Distribution

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its components, or in order to meet the performance

Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Student Dining building 6 D Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: Domestic water distribution system beyond useful

life. Replace.

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$25,260



System: D2030 - Sanitary Waste

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.

Deficiency

Location: Student Dining building 6 D Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

Notes: sanitary waste system beyond useful life. replace

Correction: Renew System

Qty: 1-Ea.

Condition Budget: \$86,004

System: D2040 - Rain Water Drainage

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was

installed in 1960. It has a 30-year service life

which expired in 1990.

Recommendation: The system should be replaced.





Deficiency

Location: Student Dining building 6 D Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years) Notes: Rain water drainage system is damaged and

beyond useful life.

Correction: Renew System

Qtv: 1-Ea. Condition Budget: \$14,434

System: D2090 - Other Plumbing Systems-Nat Gas

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2008. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2038.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3070 - Systems Testing & Balance

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

System: D4090 - Other Fire Protection Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D5010 - Electrical Service/Distribution Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5020 - Lighting and Branch Wiring Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042. Recommendation: No action is required. System: D5030 - Communications and Security Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: D5030310 - Telephone Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2005. It has a 15-year service life. Based on the assessment, it is expected to expire in 2020. Recommendation: No action is required. System: D5030910 - Fire Alarm System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: D5030910 - Security System, Camers, Access Control Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2005. It has a 15-year service life. Based on the assessment, it is expected to expire in 2020. Recommendation: No action is required.

System: D5030920 - LAN System

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5030920 - Public Address / Clock System

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E1020 - Institutional Equipment

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E2010 - Fixed Furnishings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.



Building Name: Woodshop Building 09 I

Year Built: 1960 Gross Area (SF): 3,130

The Furr High School Woodshop Building is a 1-story building. Originally built in 1960, there have been no additions, with renovations in 2012. This report contains condition and adequacy data collected during the 2012 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Building Deficiency Condition Budget Summary

| Uniformat Classification | RSLI | SCI | Condition Budget |
|---------------------------|------|---------|------------------|
| A10 Foundations | 0% | 0.00% | \$0 |
| B10 Superstructure | 0% | 0.00% | \$0 |
| B20 Exterior Enclosure | 44% | 0.00% | \$0 |
| B30 Roofing | 80% | 0.00% | \$0 |
| C10 Interior Construction | 73% | 0.00% | \$0 |
| C30 Interior Finishes | 76% | 0.00% | \$0 |
| D10 Conveying | 0% | 0.00% | \$0 |
| D20 Plumbing | 99% | 0.00% | \$0 |
| D30 HVAC | 100% | 0.00% | \$0 |
| D40 Fire Protection | 99% | 0.00% | \$0 |
| D50 Electrical | 99% | 0.00% | \$0 |
| E10 Equipment | 0% | 110.00% | \$4,880 |
| E20 Furnishings | 100% | 0.00% | \$0 |
| | | Total: | \$4,880 |


Building Deficiency Condition Budget Detail

| | | Unit | | Install | Calc Next | | | | Condition |
|-----------|-----------------------------|---------|------|---------|-----------|-------------|------|-------|-----------|
| Uniformat | System Description | Price | Life | Year | Renewal | Replacement | RSLI | SCI | Budget |
| A1010 | Standard Foundations | \$10.29 | 100 | 1960 | 2060 | \$43,480 | - | 0.00% | \$0 |
| A1030 | Slab on Grade | \$8.90 | 100 | 1960 | 2060 | \$37,607 | - | 0.00% | \$0 |
| B1020 | Roof Construction | \$16.69 | 100 | 1960 | 2060 | \$70,524 | - | 0.00% | \$0 |
| B2010 | Exterior Walls | \$18.33 | 75 | 1960 | 2035 | \$77,453 | - | 0.00% | \$0 |
| B2020 | Exterior Windows | \$12.31 | 30 | 2012 | 2042 | \$52,016 | 100% | 0.00% | \$0 |
| B2030 | Exterior Doors | \$1.05 | 30 | 2012 | 2042 | \$4,437 | 100% | 0.00% | \$0 |
| B3010105 | Built-Up | \$15.85 | 25 | 2007 | 2032 | \$66,974 | 80% | 0.00% | \$0 |
| B3020 | Roof Openings | \$0.69 | 30 | 2007 | 2037 | \$2,916 | 83% | 0.00% | \$0 |
| C1010 | Partitions | \$7.54 | 100 | 1960 | 2060 | \$31,860 | 48% | 0.00% | \$0 |
| C1020 | Interior Doors | \$4.95 | 40 | 2012 | 2052 | \$20,916 | 100% | 0.00% | \$0 |
| C1030 | Fittings | \$3.70 | 20 | 2012 | 2032 | \$15,634 | 100% | 0.00% | \$0 |
| C3010 | Wall Finishes | \$6.50 | 10 | 2012 | 2022 | \$27,466 | 100% | 0.00% | \$0 |
| C3020 | Floor Finishes | \$14.65 | 100 | 1960 | 2060 | \$61,904 | 48% | 0.00% | \$0 |
| C3030 | Ceiling Finishes | \$11.56 | 20 | 2012 | 2032 | \$48,847 | 100% | 0.00% | \$0 |
| | Escalators and Moving | | | | | | | | |
| D1020 | Walks | \$29.64 | 25 | 1960 | 1985 | \$1,200 | 0% | 0.00% | \$0 |
| D2010 | Plumbing Fixtures | \$9.26 | 30 | 2012 | 2042 | \$39,128 | 100% | 0.00% | \$0 |
| D2020 | Domestic Water Distribution | \$0.93 | 30 | 2012 | 2042 | \$3,930 | 100% | 0.00% | \$0 |
| D2030 | Sanitary Waste | \$3.16 | 30 | 2012 | 2042 | \$13,353 | 100% | 0.00% | \$0 |
| D2040 | Rain Water Drainage | \$0.53 | 30 | 2012 | 2042 | \$2,240 | 100% | 0.00% | \$0 |
| D3040 | Distribution Systems | \$12.63 | 30 | 2012 | 2042 | \$53,368 | 100% | 0.00% | \$0 |
| D3050 | Terminal & Package Units | \$13.99 | 15 | 2012 | 2027 | \$59,115 | 100% | 0.00% | \$0 |
| D3060 | Controls & Instrumentation | \$3.11 | 15 | 2012 | 2027 | \$13,141 | 100% | 0.00% | \$0 |
| D3070 | Systems Testing & Balance | \$0.91 | 30 | 2012 | 2042 | \$3,845 | 100% | 0.00% | \$0 |
| D4030 | Fire Protection Specialties | \$0.12 | 15 | 2012 | 2027 | \$507 | 100% | 0.00% | \$0 |

| Uniformat | System Description | Unit Price | Life | Install Year | Calc Next Renewal | Replacement | RSLI | SCI | Condition Budget |
|-----------|--------------------------|---------------|------|-----------------|----------------------|-------------|------|-------|---------------------|
| Official | Other Fire Protection | TILLE | LIIC | I Cai | Renewai | Replacement | KOLI | 301 | Duuget |
| D4090 | Systems | \$1.25 | 15 | 2012 | 2027 | \$5.282 | 100% | 0.00% | \$0 |
| D5030310 | Telephone Systems | \$1.25 | 15 | 2012 | 2027 | \$5,282 | 100% | 0.00% | \$0 |
| D5030910 | Fire Alarm System | \$1.57 | 10 | 2012 | 2022 | \$6,634 | 100% | 0.00% | \$0 |
| | Security System, Camers, | | | | | | | | |
| D5030910 | Access Control | \$0.82 | 15 | 2012 | 2027 | \$3,465 | 100% | 0.00% | \$0 |
| D5030920 | LAN System | \$0.82 | 15 | 2012 | 2027 | \$3,465 | 100% | 0.00% | \$0 |
| | Public Address / Clock | | | | | | | | |
| D5030920 | System | \$0.82 | 15 | 2012 | 2027 | \$3,465 | 100% | 0.00% | \$0 |
| D5090 | Other Electrical Systems | \$1.07 | 20 | 2012 | 2032 | \$4,521 | 100% | 0.00% | \$0 |
| E1090 | Other Equipment | \$1.05 | 20 | 1960 | 1980 | \$4,437 | 0% | 110% | \$4,880 |
| E2010 | Fixed Furnishings | \$3.40 | 20 | 2012 | 2032 | \$14,367 | 100% | 0.00% | \$0 |
| Total | | \$219.34 | | | | \$802,778 | 72% | 0.61% | \$4,880 |

Building Deficiency Priority


Deficiencies by Priority:



Woodshop Building 09 I Condition Budget: \$4,880



Building Deficiencies Budget Detail



Woodshop Building 09 I Condition Budget: \$4,880



Building Deficiencies Budget Narrative

System: A1010 - Standard Foundations

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: A1030 - Slab on Grade

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B1020 - Roof Construction

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060

and is non-renewable.

Recommendation: No action is required.

System: B2010 - Exterior Walls

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 75-year service life. Based on the assessment, it is expected to expire in 2035 and

is non-renewable.

Recommendation: No action is required.

System: B2020 - Exterior Windows

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: B2030 - Exterior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

Recommendation: No action is required.

•

System: B3010 - Roof Coverings

Analysis: The system Warning: unknown next-renewal

year. The system was installed at an unknown

date.

Recommendation: The system should be replaced.

System: B3010105 - Built-Up

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 25-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: B3020 - Roof Openings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2007. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2037.

Recommendation: No action is required.

System: C1010 - Partitions

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: C1020 - Interior Doors

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 40-year service life. Based on the

assessment, it is expected to expire in 2052.

Recommendation: No action is required.

System: C1030 - Fittings

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: C3010 - Wall Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the

assessment, it is expected to expire in 2022.

System: C3020 - Floor Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 1960. It has a 100-year service life. Based on the assessment, it is expected to expire in 2060.

Recommendation: No action is required.

System: C3030 - Ceiling Finishes

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: D1020 - Escalators and Moving Walks

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 25-year service life

which expired in 1985.

Recommendation: The system should be replaced.

System: D2010 - Plumbing Fixtures

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D2020 - Domestic Water Distribution

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D2030 - Sanitary Waste

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the assessment, it is expected to expire in 2042.

System: D2040 - Rain Water Drainage

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D3040 - Distribution Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D3050 - Terminal & Package Units

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3060 - Controls & Instrumentation

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

System: D3070 - Systems Testing & Balance

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 30-year service life. Based on the

assessment, it is expected to expire in 2042.

Recommendation: No action is required.

System: D4030 - Fire Protection Specialties

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the

assessment, it is expected to expire in 2027.

Recommendation: No action is required.

Final

System: D4090 - Other Fire Protection Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D5030 - Communications and Security Analysis: The system Warning: unknown next-renewal year. The system was installed at an unknown date. Recommendation: The system should be replaced. System: D5030310 - Telephone Systems Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D5030910 - Fire Alarm System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 10-year service life. Based on the assessment, it is expected to expire in 2022. Recommendation: No action is required. System: D5030910 - Security System, Camers, Access Control Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D5030920 - LAN System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027. Recommendation: No action is required. System: D5030920 - Public Address / Clock System Analysis: The system is in use and functioning with an estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 15-year service life. Based on the assessment, it is expected to expire in 2027.

FOR OFFICIAL USE ONLY

System: D5090 - Other Electrical Systems

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.

Recommendation: No action is required.

System: E1090 - Other Equipment

Analysis: The system age is either beyond expected life or

does not meet its intended performance under the Guidelines. The system may be in service and functioning but it is recommended to be replaced due to probable increased condition budget needs, the potential failure of its

components, or in order to meet the performance Guidelines for this system. The system was installed in 1960. It has a 20-year service life

which expired in 1980.

Recommendation: The system should be replaced.

Deficiency

Location: Woodshop Building 09 I Distress: Beyond Expected Life Category: Deferred Maintenance

Priority: 3 - Short Term Conditions (2-3 Years)

System: E2010 - Fixed Furnishings

Notes: sawdust vaccum system inoperative. Repair or

replace

Correction: Renew System

Qty: 1-Ea. Condition Budget: \$4,880

Analysis: The system is in use and functioning with an

estimated remaining service life as indicated in the report section "Condition/Replacement Budget Detail". The system was installed in 2012. It has a 20-year service life. Based on the

assessment, it is expected to expire in 2032.



Appendix 1 - Assessment Criteria

Assessment Criteria

| Task No | Task Description | Score | Comments |
|---------|-------------------------------------------------|-------|----------|
| 1000.00 | Facility Condition | | |
| 1000.00 | What is the Building's facility condition based | N/A | |
| | on its facility condition index? | | |
| 2000.00 | Educational Suitability | | |
| 2000.00 | What is the educational suitability score for | N/A | |
| | this school as determined by MGT in 2012? | | |
| 3000.00 | Technology Readiness | | |
| 3000.00 | What is the technology readiness score as | N/A | |
| | determined by MGT in 2012? | | |



Glossary

Abandoned A facility owned by a district that is not occupied and not maintained. See Vacant.

Building A fully enclosed and roofed structure that can be traversed internally without exiting to the

exterior.

Building addition An area, space or component of a building added to a building after the original building's

year built date. "Main" is used to designate the original building. Additions built prior to 1980 were included in the Main building area calculations to reflect their predicted system

depreciation characteristics and remaining useful life.

Calculated Next Renewal Calculated Next Renewal refers to the year a system or building element completes its

useful life based on its installed date and its expected useful or design life.

Capital Renewal Capital Renewal refers to physical facility condition work (excluding suitability and

technology work) that includes the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life that is not normally included in an annual

operating maintenance budget.

Category Category refers to the type or class of a user defined deficiency grouping with shared or

similar characteristics. Category descriptions are:

Condition Condition refers to the state of physical fitness or readiness of a facility system or system

element for its intended use.

Condition Budget The Condition Budget, also known as Condition Needs, represents the budgeted

contractor installed costs plus owner's soft costs for the repair, replacement or renewal for

a component or system level deficiency. It excludes contributing costs for other

components or systems that might also be associated with the cortrective actions due to

packaging the work.

Condition Score Condition Score is a factor used in the calculation of School Score expressed as

Correction Correction refers to an assessor's recommended deficiency repair or replacement action.

For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a material defined in a Uniformat II element, or system it is intended to address. It excludes other peripheral costs

that may also be included in the pacakaging of repair, replacement or renewal

improvements that may also be triggered by the deficiency correction.

Criteria Criteria refers to the set of requirements, guidelines or standards that are assessed and

rated to develop a score.

Current Period The Current Period is the curent year plus a user defined number of forward years.

Current Replacement Value

(CRV)

Current Replacement Value (CRV), also known as Replacement Value represents the hypothetical total cost of rebuilding or replacing an existing facility in current dollars to an

optimal state-of-the-art condition under current codes and construction standards and

techniques.

Deferred maintenance Deferred maintenance is condition work (excluding suitability and technology readiness

needs) deferred on a planned or unplanned basis to a future budget cycle or postponed

until funds are available.

Deficiency A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an

intended purpose.

Distress Distress refers to a user defined root cause of a deficiency. Distress descriptions are:

Element Elements are the major components that comprise building systems as defined by

Uniformat.

Extended Facility Condition

Index (EFCI)

Extended Facility Condition Index (EFCI) is calculated as the condition needs for the current year plus facility system renewal for user defined forward years (the Current

Period) divided by Current Replacement Value.

Facility A facility refers to site(s), building(s), or building addition(s), or combinations thereof that

provide a particular service or support of an educational purpose.

Facility Condition Index (FCI) FCI is an industry-standard measurement of facility condition calculated as the ratio of the

costs to correct a facility's deficiencies to the facility's Current Replacement Value. It

ranges from 0% (new) to 100%(very poor).

Forecast Period The Forecast Period refers to a user defined number of years after the Current Period.

The area of the enclosed floor space of a building or building addition in square feet Gross square feet (GSF)

measured to the outside face of the enclosing wall.

The year a system or element was built or the most recent major renovation date where a Install year

minimum of 70% of the system's Current Replacement Value (CRV) was replaced.

Life cycle refers to the period of time that a building or or element exists and can serve its Life cycle

intended function. The cycle includes warranty period, intrinsic period, and run to failure

period. (See Useful Life)

Next Renewal Next Renewal refers to a manually adjusted expected useful life of a system or element

based on on-site inspection either by reducing or extending the Calculated Next Renewal

to more accurately current conditions.

Order of Magnitude Order of Magnitude refers to a rough approximation made with a degree of knowledge and

confidence that the budgeted, projected or estimated cost falls within a reasonable range

of cost values.

Priority Priority refers to a deficiency's urgency for repair as determined by the assessment team.

Remaining Service Life % is a calculated value such that RSL% = RSL divided by its Remaining Service Life %

system Design Life (not displayed).

Remaining Service Life

(RSL)

Remaining service life is a measure of a system's or element's predicted remaining useful life calculated as RSL = Next Renewal or Calculated Next Renewal Year minus the

Current Year.

Remaining Service Life

Index (RSLI)

The Remaining Service Life Index (RSLI) also known as the Condition Index (CI) is calculated as the sum of a renewable systems Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude softcost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to

0.00% (expired - no remaining life).

See Current Replacement Value.

Remaining Service Life

Value

Remaining Service Life Value also known as the RSL Weight is a calculated value used to

determine the RSLI that is equal to the system Value (Unit Cost * Qty) * RSL (not

displayed).

Replacement Value

Site

A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land

improvements needed to support a facility.

Soft Costs Soft Costs are a construction industry term that refers to expense items that are not

> considered direct construction costs. Soft costs are user defined and include architectural, engineering, management, testing, and mitagation fees, and other owner pre- and post-

construction expenses.

Suitability Suitability refers to the measure of how well a facility supports the educational program(s)

that it houses based on criteria derived from state laws, guidelines and national

educational best practices.

Suitability Score Suitability Score is a calculated value expressed as

System refers to building and related site work elements as described by ASTM Uniformat System

II Classification for Building Elements (E1557-97) a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also Uniformat II.

System Condition Index

(SCI)

System Condition Index (SCI) is the ratio of a system's current condition deficiency costs to its replacement value - also known as "percent used" ranging from 0 percent to 100

percent or greater due to the addition of the system's renewal premium the additional

costs to prepare for the system renewal such as demolition costs.

Technology Score Technology Score, also known as Technology Readiness Score, is calculated as follows:

(Sum of scoring for technology readiness criteria issues) * weighted value.

Uniformat, also known as Uniformat II, a publication of the Construction Specification

Institute (CSI), is ASTM Uniformat II Classification for Building Elements (E1557-97). UniFormat is a method of arranging construction information based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or

assemblies.

Useful Life Useful Life refers to the intrinsic period of time a system or element is expected to perform

as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in this project are derived from the Building Owners and Managers (BOMA) organization's guidelines,

RSMeans cost data, and from user defined historical experience.

Utilization Utilization, also known as School Utilization, refers to ratio of students to the school's

capacity calculated by dividing the number enrolled at the school by its Program Capacity.

Vacant Vacant refers to a facility that is not occupied but is a maintained facility by a district. See

Abandoned.

Weight (Weighting Factor) Weight, also known as Weighting Factor, is a user defined factor used to apply more or

less emphasis to system or element attributes such as deficiency category, deficiency priority or functional adequacy standard. For example, \$100 of a Priority 1 issue by default has the same cost value (1x) as \$100 of a Priority 5 item. Using weighting factors, the user can establish a priority factor so that for ranking or sorting purposes the facility (District, School, Building, Room, etc.) with a greater weighting (say 2x) thereby elevating it in rank

order over the facility with Priority 1.

Year built The year that a building or addition was originally built based on its date of substantial

completion or occupancy.

